

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
95064	506	528 W	10TH		ST	LOCAL	43	313	60	18,780	43,029	Reconstruct		\$49.00	\$303,672.60
95581	400	428 W	10TH		ST	LOCAL	25	324	60	19,440		Reconstruct		\$49.00	\$314,344.80
95583	300	328 W	10TH		ST	LOCAL	28	316	55	17,380		Reconstruct		\$49.00	\$281,034.60
94669	200	228 W	10TH		ST	LOCAL	49	320	60	19,200		Mill & Overlay		\$15.00	\$95,040.00
95140	700	724 W	10TH		ST	LOCAL	51	378	35	13,230		Mill & Overlay		\$15.00	\$65,488.50
95264	1000	1028 W	10TH		ST	LOCAL	53	429	30	12,870		Coated Chip		\$2.95	\$4,176.32
95260	726	818 W	10TH		ST	LOCAL	55	312	35	10,920		Mill & Overlay		\$15.00	\$54,054.00
95745	100	128 W	10TH		ST	LOCAL	58	338	65	21,970		Mill & Overlay		\$15.00	\$108,751.50
95112	600	698 W	10TH		ST	LOCAL	63	232	100	23,200		Mill & Overlay		\$15.00	\$114,840.00
95262	820	998 W	10TH		ST	LOCAL	63	1016	25	25,400		Coated Chip		\$2.95	\$8,242.30
96288	1170	1198 W	10TH		ST	LOCAL		300	25	7,500		Mill & Overlay		\$15.00	\$37,125.00
96786	1100	1138 W	10TH		ST	LOCAL		206	30	6,180		Mill & Overlay		\$15.00	\$30,591.00
96941	500	504 W	10TH		ST	LOCAL		25	70	1,750		Mill & Overlay		\$15.00	\$8,662.50
													Total:	\$1,426,023.12	
95719	500	548 E	11TH		ST	LOCAL		800	20	16,000		Crack Seal		\$0.75	\$1,320.00
95721	300	348 E	11TH		ST	LOCAL		515	15	7,725		Crack Seal		\$0.75	\$637.31
95722	400	420 E	11TH		ST	LOCAL		900	25	22,500		Crack Seal		\$0.75	\$1,856.25
95751	100	228 E	11TH		ST	LOCAL		792	30	23,760		Crack Seal		\$0.75	\$1,960.20
													Total:	\$5,773.76	
94678	300	328 W	1ST		ST	LOCAL		315	40	12,600		Coated Chip		\$2.95	\$4,088.70
94706	100	128 E	1ST		ST	LOCAL		333	35	11,655		Uncoated Chip		\$2.50	\$3,205.13
94829	400	428 W	1ST		ST	LOCAL		337	40	13,480		Coated Chip		\$2.95	\$4,374.26
95125	100	128 W	1ST		ST	LOCAL		336	40	13,440		Coated Chip		\$2.95	\$4,361.28
95138	600	600 W	1ST		ST	LOCAL		378	70	26,460		Coated Chip		\$2.95	\$8,586.27
95562	200	218 W	1ST		ST	LOCAL		313	40	12,520		Coated Chip		\$2.95	\$4,062.74
95615	200	228 E	1ST		ST	LOCAL		162	30	4,860		Uncoated Chip		\$2.50	\$1,336.50
95631	400	430 E	1ST		ST	LOCAL		587	30	17,610		Uncoated Chip		\$2.50	\$4,842.75
95639	300	330 E	1ST		ST	LOCAL		316	30	9,480		Uncoated Chip		\$2.50	\$2,607.00
96329	500	528 W	1ST		ST	LOCAL		374	70	26,180		Coated Chip		\$2.95	\$8,495.41
													Total:	\$45,960.04	
94665	300	328 W	2ND		ST	LOCAL		645	40	25,800		Uncoated Chip		\$2.50	\$7,095.00
94767	100	128 W	2ND		ST	LOCAL		341	40	13,640		Uncoated Chip		\$2.50	\$3,751.00
94795	200	228 W	2ND		ST	LOCAL		280	30	8,400		Uncoated Chip		\$2.50	\$2,310.00
95026	500	528 W	2ND		ST	LOCAL		370	30	11,100		Uncoated Chip		\$2.50	\$3,052.50
95623	200	228 E	2ND		ST	LOCAL		156	30	4,680		Crack Seal		\$0.75	\$386.10
95624	400	430 E	2ND		ST	LOCAL		319	30	9,570		Crack Seal		\$0.75	\$789.53
95626	100	128 E	2ND		ST	LOCAL		332	30	9,960		Crack Seal		\$0.75	\$821.70
95629	300	330 E	2ND		ST	LOCAL		318	30	9,540		Crack Seal		\$0.75	\$787.05
													Total:	\$18,992.88	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
94695	300	328	W	4TH	ST	LOCAL		319	30	9,570		Crack Seal		\$0.75	\$789.53
94834	100	128	W	4TH	ST	LOCAL		330	40	13,200		Crack Seal		\$0.75	\$1,089.00
94918	200	228	E	4TH	ST	LOCAL		329	30	9,870		Crack Seal		\$0.75	\$814.28
94985	700	728	E	4TH	ST	LOCAL		310	30	9,300		Crack Seal		\$0.75	\$767.25
95144	400	428	W	4TH	ST	LOCAL		325	30	9,750		Crack Seal		\$0.75	\$804.38
95560	200	228	W	4TH	ST	LOCAL		326	30	9,780		Crack Seal		\$0.75	\$806.85
95642	100	128	E	4TH	ST	LOCAL		328	40	13,120		Crack Seal		\$0.75	\$1,082.40
95644	400	428	E	4TH	ST	LOCAL		312	30	9,360		Crack Seal		\$0.75	\$772.20
													Total:	\$6,925.88	
94843	100	128	E	5TH	ST	LOCAL		325	40	13,000		Crack Seal		\$0.75	\$1,072.50
95098	400	428	W	5TH	ST	LOCAL		332	35	11,620		Crack Seal		\$0.75	\$958.65
95120	100	128	W	5TH	ST	LOCAL		331	40	13,240		Crack Seal		\$0.75	\$1,092.30
95563	300	328	W	5TH	ST	LOCAL		320	35	11,200		Crack Seal		\$0.75	\$924.00
95565	200	228	W	5TH	ST	LOCAL		322	40	12,880		Crack Seal		\$0.75	\$1,062.60
95589	500	508	W	5TH	ST	LOCAL		348	30	10,440		Crack Seal		\$0.75	\$861.30
95625	300	330	E	5TH	ST	LOCAL		319	30	9,570		Crack Seal		\$0.75	\$789.53
95628	200	228	E	5TH	ST	LOCAL		330	30	9,900		Crack Seal		\$0.75	\$816.75
95633	400	430	E	5TH	ST	LOCAL		321	25	8,025		Crack Seal		\$0.75	\$662.06
95665	800	828	E	5TH	ST	LOCAL		312	25	7,800		Crack Seal		\$0.75	\$643.50
													Total:	\$8,883.19	
95663	600	620	E	6TH	ST	LOCAL	57	325	40	13,000	7,884	Coated Chip		\$2.95	\$4,218.50
94850	1000	1030	E	6TH	ST	LOCAL	63	800	30	24,000	4,841	Coated Chip		\$2.95	\$7,788.00
94982	300	330	E	6TH	ST	LOCAL	53	320	40	12,800		Coated Chip		\$2.95	\$4,153.60
95028	200	228	E	6TH	ST	LOCAL	53	320	40	12,800		Coated Chip		\$2.95	\$4,153.60
94747	100	128	E	6TH	ST	LOCAL	54	330	50	16,500		Coated Chip		\$2.95	\$5,354.25
94934	900	930	E	6TH	ST	LOCAL	54	460	30	13,800		Coated Chip		\$2.95	\$4,478.10
94929	800	828	E	6TH	ST	LOCAL	56	360	40	14,400		Coated Chip		\$2.95	\$4,672.80
94803	504	510	E	6TH	ST	LOCAL	57	410	40	16,400		Coated Chip		\$2.95	\$5,321.80
95655	400	430	E	6TH	ST	LOCAL	57	335	40	13,400		Coated Chip		\$2.95	\$4,348.30
94713	1100	1130	E	6TH	ST	LOCAL	64	800	30	24,000		Coated Chip		\$2.95	\$7,788.00
95658	700	728	E	6TH	ST	LOCAL	64	320	40	12,800		Coated Chip		\$2.95	\$4,153.60
94921	200	228	W	6TH	ST	LOCAL		520	45	23,400		Coated Chip		\$2.95	\$7,593.30
95012	100	128	W	6TH	ST	LOCAL		340	45	15,300		Coated Chip		\$2.95	\$4,964.85
95050	400	428	W	6TH	ST	LOCAL		310	40	12,400		Coated Chip		\$2.95	\$4,023.80
95566	300	328	W	6TH	ST	LOCAL		235	40	9,400		Coated Chip		\$2.95	\$3,050.30
													Total:	\$76,062.80	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
94833	400	428 W	7TH		ST	LOCAL		320	30	9,600		Uncoated Chip		\$2.50	\$2,640.00
94891	400	430 E	7TH		ST	LOCAL		290	25	7,250		Uncoated Chip		\$2.50	\$1,993.75
94910	200	228 W	7TH		ST	LOCAL		315	30	9,450		Uncoated Chip		\$2.50	\$2,598.75
94944	100	128 W	7TH		ST	LOCAL		320	40	12,800		Uncoated Chip		\$2.50	\$3,520.00
94954	600	608 W	7TH		ST	LOCAL		215	30	6,450		Uncoated Chip		\$2.50	\$1,773.75
95588	500	508 W	7TH		ST	LOCAL		645	30	19,350		Uncoated Chip		\$2.50	\$5,321.25
95616	200	228 E	7TH		ST	LOCAL		330	30	9,900		Uncoated Chip		\$2.50	\$2,722.50
95620	300	330 E	7TH		ST	LOCAL		315	30	9,450		Uncoated Chip		\$2.50	\$2,598.75
95635	100	128 E	7TH		ST	LOCAL		330	40	13,200		Uncoated Chip		\$2.50	\$3,630.00
95656	800	828 E	7TH		ST	LOCAL		352	35	12,320		Uncoated Chip		\$2.50	\$3,388.00
													Total:	\$30,186.75	
94736	500	528 W	8TH		ST	LOCAL		307	30	9,210		Uncoated Chip		\$2.50	\$2,532.75
94783	100	128 W	8TH		ST	LOCAL		322	40	12,880		Uncoated Chip		\$2.50	\$3,542.00
94813	400	428 W	8TH		ST	LOCAL		319	50	15,950		Uncoated Chip		\$2.50	\$4,386.25
94975	600	698 W	8TH		ST	LOCAL		369	30	11,070		Uncoated Chip		\$2.50	\$3,044.25
95617	100	128 E	8TH		ST	LOCAL		330	40	13,200		Uncoated Chip		\$2.50	\$3,630.00
95634	200	228 E	8TH		ST	LOCAL		166	30	4,980		Uncoated Chip		\$2.50	\$1,369.50
95637	300	330 E	8TH		ST	LOCAL		318	30	9,540		Uncoated Chip		\$2.50	\$2,623.50
95638	400	430 E	8TH		ST	LOCAL		316	30	9,480		Uncoated Chip		\$2.50	\$2,607.00
													Total:	\$23,735.25	
95677	1000	1006 E	9TH		ST	LOCAL	61	390	50	19,500	2,005	Uncoated Chip		\$2.50	\$5,362.50
94684	600	698 W	9TH		ST	LOCAL		293	30	8,790		Uncoated Chip		\$2.50	\$2,417.25
94719	300	328 W	9TH		ST	LOCAL		323	30	9,690		Uncoated Chip		\$2.50	\$2,664.75
94890	100	128 W	9TH		ST	LOCAL		324	30	9,720		Uncoated Chip		\$2.50	\$2,673.00
94998	500	528 W	9TH		ST	LOCAL		311	30	9,330		Uncoated Chip		\$2.50	\$2,565.75
95039	200	228 W	9TH		ST	LOCAL		331	30	9,930		Uncoated Chip		\$2.50	\$2,730.75
95582	400	428 W	9TH		ST	LOCAL		322	30	9,660		Uncoated Chip		\$2.50	\$2,656.50
95618	200	228 E	9TH		ST	LOCAL		161	30	4,830		Uncoated Chip		\$2.50	\$1,328.25
95619	400	430 E	9TH		ST	LOCAL		333	30	9,990		Uncoated Chip		\$2.50	\$2,747.25
95622	100	128 E	9TH		ST	LOCAL		331	40	13,240		Uncoated Chip		\$2.50	\$3,641.00
95641	300	330 E	9TH		ST	LOCAL		321	30	9,630		Uncoated Chip		\$2.50	\$2,648.25
													Total:	\$31,435.25	
94772	200	218		ABILENE	ST	LOCAL		394	30	11,820		Uncoated Chip		\$2.50	\$3,250.50
95847	100	110		ABILENE	ST	LOCAL		360	30	10,800		Uncoated Chip		\$2.50	\$2,970.00
96309	128	138		ABILENE	ST	LOCAL		356	30	10,680		Uncoated Chip		\$2.50	\$2,937.00
													Total:	\$9,157.50	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
95573	300	328	W	ADAMS	ST	LOCAL		651	30	19,530		Uncoated Chip		\$2.50	\$5,370.75
95575	200	228	W	ADAMS	ST	LOCAL		653	30	19,590		Uncoated Chip		\$2.50	\$5,387.25
95651	200	228	E	ADAMS	ST	LOCAL		662	30	19,860		Uncoated Chip		\$2.50	\$5,461.50
95653	400	430	E	ADAMS	ST	LOCAL		453	30	13,590		Uncoated Chip		\$2.50	\$3,737.25
													Total:	\$19,956.75	
95320	2	50		ADOBE	TRL			414	40	16,560		Uncoated Chip		\$2.50	\$4,554.00
													Total:	\$4,554.00	
94716	600	630		ALABAMA	ST	LOCAL		442	30	13,260		Uncoated Chip		\$2.50	\$3,646.50
95082	500	532		ALABAMA	ST	LOCAL		466	30	13,980		Uncoated Chip		\$2.50	\$3,844.50
95102	400	430		ALABAMA	ST	LOCAL		443	30	13,290		Uncoated Chip		\$2.50	\$3,654.75
97228	700	718		ALABAMA	ST	LOCAL		552	30	16,560		Uncoated Chip		\$2.50	\$4,554.00
													Total:	\$15,699.75	
95255	700	724		ALLRED	ST	LOCAL		427	50	21,350		None		\$0.00	\$0.00
													Total:	\$0.00	
95428	101	125		AMARYLLIS	ST	LOCAL	28	1000	35	35,000		Mill & Overlay		\$15.00	\$173,250.00
													Total:	\$173,250.00	
95742	1100	1128		ANDRESS	ST	LOCAL		865	30	25,950		Uncoated Chip		\$2.50	\$7,136.25
													Total:	\$7,136.25	
95142	100	108		ANTELOPE	ST	LOCAL	52	305	30	9,150		Uncoated Chip		\$2.50	\$2,516.25
95430	200	218		ANTELOPE	ST	LOCAL	75	251	25	6,275		Crack Seal		\$0.75	\$517.69
													Total:	\$3,033.94	
94970	100	220		ARLINE	ST	LOCAL		1386	20	27,720		Uncoated Chip		\$2.50	\$7,623.00
													Total:	\$7,623.00	
95429	100	122		ASH	ST	LOCAL		736	30	22,080		Uncoated Chip		\$2.50	\$6,072.00
													Total:	\$6,072.00	
95815	400	408		ASPEN	ST	LOCAL		324	30	9,720		Uncoated Chip		\$2.50	\$2,673.00
													Total:	\$2,673.00	
95407	200	214		AUGUSTA	ST	LOCAL		688	35	24,080		Uncoated Chip		\$2.50	\$6,622.00
													Total:	\$6,622.00	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
94751	500	508		AUSTIN	ST	LOCAL		306	30	9,180		Uncoated Chip		\$2.50	\$2,524.50
94967	510	618		AUSTIN	ST	LOCAL		427	30	12,810		Uncoated Chip		\$2.50	\$3,522.75
94990	300	324		AUSTIN	ST	LOCAL		915	30	27,450		Uncoated Chip		\$2.50	\$7,548.75
													Total:	\$13,596.00	
95422	100	142		AVALON	ST	LOCAL		1341	30	40,230		Uncoated Chip		\$2.50	\$11,063.25
													Total:	\$11,063.25	
95019	800	814		BAGWELL	ST	LOCAL		547	30	16,410		Uncoated Chip		\$2.50	\$4,512.75
													Total:	\$4,512.75	
95885	101	111		BAIRD	ST	LOCAL		376	30	11,280		Uncoated Chip		\$2.50	\$3,102.00
													Total:	\$3,102.00	
94935	1400	1412		BAKER	ST	LOCAL		446	30	13,380		Uncoated Chip		\$2.50	\$3,679.50
94957	1200	1230		BAKER	ST	LOCAL		418	30	12,540		Uncoated Chip		\$2.50	\$3,448.50
95718	1348	1364		BAKER	ST	LOCAL		579	35	20,265		Uncoated Chip		\$2.50	\$5,572.88
													Total:	\$12,700.88	
95794	1500	1524		BALIN	ST	LOCAL		685	35	23,975		Uncoated Chip		\$2.50	\$6,593.13
													Total:	\$6,593.13	
94827	800	834		BARTUSH	ST	LOCAL	59	1079	30	32,370	684	Uncoated Chip		\$2.50	\$8,901.75
94781	700	728		BARTUSH	ST	LOCAL		814	30	24,420		Uncoated Chip		\$2.50	\$6,715.50
													Total:	\$15,617.25	
94913	300	316		BAYLOR	ST	LOCAL		442	30	13,260		Uncoated Chip		\$2.50	\$3,646.50
95805	400	420		BAYLOR	ST	LOCAL		522	30	15,660		Uncoated Chip		\$2.50	\$4,306.50
													Total:	\$7,953.00	
95813	400	406		BEECH	ST	LOCAL		273	30	8,190		Uncoated Chip		\$2.50	\$2,252.25
													Total:	\$2,252.25	
95662	900	906		BEVERLY	DR	LOCAL		1420	50	71,000		Uncoated Chip		\$2.50	\$19,525.00
													Total:	\$19,525.00	
95771	1400	1420		BLUEBONNET	ST	LOCAL		944	30	28,320		Uncoated Chip		\$2.50	\$7,788.00
													Total:	\$7,788.00	
94889	500	528		BOWIE	ST	LOCAL		591	30	17,730		Uncoated Chip		\$2.50	\$4,875.75
													Total:	\$4,875.75	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
95680	1000	1030		BOWMAN	DR	LOCAL		1164	30	34,920		Uncoated Chip		\$2.50	\$9,603.00
													Total:	\$9,603.00	
94828	1200	1216		BOYD	ST	LOCAL	55	610	30	18,300	1,334	Uncoated Chip		\$2.50	\$5,032.50
94787	1100	1114		BOYD	ST	LOCAL	45	509	30	15,270	1,232	Uncoated Chip		\$2.50	\$4,199.25
95702	1604	1610		BOYD	ST	LOCAL	56	279	30	8,370	1,050	Uncoated Chip		\$2.50	\$2,301.75
95004	1300	1314		BOYD	ST	LOCAL	44	544	30	16,320		Uncoated Chip		\$2.50	\$4,488.00
94996	1400	1424		BOYD	ST	LOCAL	45	825	30	24,750		Uncoated Chip		\$2.50	\$6,806.25
95701	1500	1598		BOYD	ST	LOCAL	51	811	30	24,330		Uncoated Chip		\$2.50	\$6,690.75
95707	1800	1820		BOYD	ST	LOCAL	52	697	30	20,910		Uncoated Chip		\$2.50	\$5,750.25
95116	1700	1710		BOYD	ST	LOCAL	58	463	30	13,890		Uncoated Chip		\$2.50	\$3,819.75
95706	1900	1900		BOYD	ST	LOCAL		201	55	11,055		Uncoated Chip		\$2.50	\$3,040.13
													Total:	\$42,128.63	
94671	1200	1298		BRAIN	ST	LOCAL		357	20	7,140		Uncoated Chip		\$2.50	\$1,963.50
94687	300	330		BRAIN	ST	LOCAL		490	30	14,700		None		\$0.00	\$0.00
94696	500	532		BRAIN	ST	LOCAL		456	30	13,680		None		\$0.00	\$0.00
94815	700	730		BRAIN	ST	LOCAL		595	30	17,850		Uncoated Chip		\$2.50	\$4,908.75
94848	1000	1048		BRAIN	ST	LOCAL		608	20	12,160		Uncoated Chip		\$2.50	\$3,344.00
95001	1100	1198		BRAIN	ST	LOCAL		521	25	13,025		Uncoated Chip		\$2.50	\$3,581.88
95092	800	830		BRAIN	ST	LOCAL		444	30	13,320		Uncoated Chip		\$2.50	\$3,663.00
													Total:	\$17,461.13	
95366	100	128		BRIERWOOD	ST	LOCAL		1147	30	34,410		Uncoated Chip		\$2.50	\$9,462.75
													Total:	\$9,462.75	
95353	500	510		BROADMOOR	ST	LOCAL	66	475	40	19,000	8,770	Mill & Overlay		\$15.00	\$94,050.00
95351	400	408		BROADMOOR	ST	LOCAL	58	611	40	24,440	6,888	Mill & Overlay		\$15.00	\$120,978.00
95348	128	132		BROADMOOR	ST	LOCAL	43	307	40	12,280		Mill & Overlay		\$15.00	\$60,786.00
96708	100	126		BROADMOOR	ST	LOCAL	43	1600	40	64,000		Mill & Overlay		\$15.00	\$316,800.00
95354	700	710		BROADMOOR	ST	LOCAL	49	135	40	5,400		Mill & Overlay		\$15.00	\$26,730.00
95349	206	210		BROADMOOR	ST	LOCAL	52	323	40	12,920		Mill & Overlay		\$15.00	\$63,954.00
95350	300	304		BROADMOOR	ST	LOCAL	54	315	40	12,600		Mill & Overlay		\$15.00	\$62,370.00
													Total:	\$745,668.00	
95777	200	216		BROWN	ST	LOCAL		633	30	18,990		Uncoated Chip		\$2.50	\$5,222.25
													Total:	\$5,222.25	
95820	200	218		BRUSH	ST	LOCAL		706	30	21,180		Uncoated Chip		\$2.50	\$5,824.50
													Total:	\$5,824.50	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
95018	300	324	N	BRYAN	ST	LOCAL		889	30	26,670		Uncoated Chip		\$2.50	\$7,334.25
95110	100	128	N	BRYAN	ST	LOCAL		282	40	11,280		Uncoated Chip		\$2.50	\$3,102.00
95609	100	298	S	BRYAN	ST	LOCAL		659	40	26,360		Uncoated Chip		\$2.50	\$7,249.00
													Total:	\$17,685.25	
95268	800	824		BUCKNER	ST	LOCAL		681	25	17,025		Uncoated Chip		\$2.50	\$4,681.88
													Total:	\$4,681.88	
95281	100	1198		BULLDOG	BLVD	LOCAL		1655	40	66,200		Mill & Overlay		\$15.00	\$327,690.00
97217	1300	1498		BULLDOG	BLVD	LOCAL		850	25	21,250		Mill & Overlay		\$15.00	\$105,187.50
													Total:	\$432,877.50	
95399	101	109		BUNAVISTA	ST	LOCAL		266	40	10,640		Uncoated Chip		\$2.50	\$2,926.00
													Total:	\$2,926.00	
94727	200	208		BUNTON	ST	LOCAL	43	309	45	13,905		Uncoated Chip		\$2.50	\$3,823.88
95873	118	124		BUNTON	ST	LOCAL	50	616	35	21,560		Uncoated Chip		\$2.50	\$5,929.00
97037	300	304		BUNTON	ST	LOCAL		174	20	3,480		Uncoated Chip		\$2.50	\$957.00
													Total:	\$10,709.88	
94682	1400	1410		BURCH	ST	LOCAL		447	25	11,175		Uncoated Chip		\$2.50	\$3,073.13
													Total:	\$3,073.13	
95385	101	105		BUTADIENO	ST	LOCAL		281	50	14,050		Uncoated Chip		\$2.50	\$3,863.75
95386	201	207		BUTADIENO	ST	LOCAL		341	50	17,050		Uncoated Chip		\$2.50	\$4,688.75
95393	401	411		BUTADIENO	ST	LOCAL		380	40	15,200		Uncoated Chip		\$2.50	\$4,180.00
95394	501	511		BUTADIENO	ST	LOCAL		246	55	13,530		Uncoated Chip		\$2.50	\$3,720.75
													Total:	\$16,453.25	
96559	300	328		CACTUS	ST	LOCAL	50	1531	20	30,620		Uncoated Chip		\$2.50	\$8,420.50
96560	330	368		CACTUS	ST	LOCAL	50	1167	20	23,340		Uncoated Chip		\$2.50	\$6,418.50
													Total:	\$14,839.00	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
95380	501	507		CALICHE	ST	LOCAL		229	40	9,160		Uncoated Chip		\$2.50	\$2,519.00
95381	401	409		CALICHE	ST	LOCAL		360	40	14,400		Uncoated Chip		\$2.50	\$3,960.00
95382	301	315		CALICHE	ST	LOCAL		598	40	23,920		Uncoated Chip		\$2.50	\$6,578.00
95383	201	211		CALICHE	ST	LOCAL		452	40	18,080		Uncoated Chip		\$2.50	\$4,972.00
95384	101	107		CALICHE	ST	LOCAL		269	40	10,760		Uncoated Chip		\$2.50	\$2,959.00
													Total:	\$20,988.00	
94717	600	630		CALIFORNIA	ST	LOCAL		443	30	13,290		Uncoated Chip		\$2.50	\$3,654.75
94801	500	532		CALIFORNIA	ST	LOCAL		452	30	13,560		Uncoated Chip		\$2.50	\$3,729.00
94876	700	724		CALIFORNIA	ST	LOCAL		441	30	13,230		Uncoated Chip		\$2.50	\$3,638.25
94971	400	430		CALIFORNIA	ST	LOCAL		457	30	13,710		Uncoated Chip		\$2.50	\$3,770.25
													Total:	\$14,792.25	
95481	1200	1230		CAMPUS	PL	LOCAL		252	75	18,900		Uncoated Chip		\$2.50	\$5,197.50
													Total:	\$5,197.50	
95269	900	924		CANADY	ST	LOCAL	50	311	30	9,330	1,657	Coated Chip		\$2.95	\$3,027.59
95044	810	820		CANADY	ST	LOCAL	64	343	30	10,290	1,646	Coated Chip		\$2.95	\$3,339.11
94902	926	998		CANADY	ST	LOCAL	62	328	30	9,840		Coated Chip		\$2.95	\$3,193.08
95257	800	808		CANADY	ST	LOCAL	63	312	30	9,360		Coated Chip		\$2.95	\$3,037.32
													Total:	\$12,597.09	
95802	1500	1518		CANYON	DR	LOCAL		804	30	24,120		Uncoated Chip		\$2.50	\$6,633.00
													Total:	\$6,633.00	
95396	101	109		CAPROCK	ST	LOCAL		167	30	5,010		Uncoated Chip		\$2.50	\$1,377.75
													Total:	\$1,377.75	
95686	1110	1120		CARPENTER	ST	LOCAL	57	380	30	11,400		Uncoated Chip		\$2.50	\$3,135.00
95682	1004	1012		CARPENTER	ST	LOCAL		360	30	10,800		Uncoated Chip		\$2.50	\$2,970.00
96945	1000	1002		CARPENTER	ST	LOCAL		135	25	3,375		Uncoated Chip		\$2.50	\$928.13
													Total:	\$7,033.13	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
95364	100	128		CASTLE	DR	LOCAL		1007	30	30,210		Uncoated Chip		\$2.50	\$8,307.75
													Total:	\$8,307.75	
95060	111	199		CHAPARRAL	ST	LOCAL		265	40	10,600		Uncoated Chip		\$2.50	\$2,915.00
95424	201	221		CHAPARRAL	ST	LOCAL		520	40	20,800		Uncoated Chip		\$2.50	\$5,720.00
95425	101	109		CHAPARRAL	ST	LOCAL		759	30	22,770		Uncoated Chip		\$2.50	\$6,261.75
													Total:	\$14,896.75	
94909	1000	1010		CHAPMAN	ST	LOCAL		292	25	7,300		Uncoated Chip		\$2.50	\$2,007.50
95261	900	910		CHAPMAN	ST	LOCAL		286	25	7,150		Uncoated Chip		\$2.50	\$1,966.25
													Total:	\$3,973.75	
94817	712	728		CHEATHAM	ST	LOCAL		402	30	12,060		Uncoated Chip		\$2.50	\$3,316.50
													Total:	\$3,316.50	
95887	1514	1516		CLAYTON	ST	LOCAL	62	287	30	8,610	1,825	Uncoated Chip		\$2.50	\$2,367.75
94778	1400	1426		CLAYTON	ST	LOCAL	62	1138	30	34,140	1,489	Uncoated Chip		\$2.50	\$9,388.50
95066	1300	1320		CLAYTON	ST	LOCAL	53	714	30	21,420	679	Uncoated Chip		\$2.50	\$5,890.50
94709	1500	1502		CLAYTON	ST	LOCAL	59	160	30	4,800		Uncoated Chip		\$2.50	\$1,320.00
95883	1504	1512		CLAYTON	ST	LOCAL	60	372	30	11,160		Uncoated Chip		\$2.50	\$3,069.00
													Total:	\$22,035.75	
95505	1100	1128		CLEVELAND	ST	LOCAL		724	30	21,720		Uncoated Chip		\$2.50	\$5,973.00
													Total:	\$5,973.00	
95739	1100	1112		COBLE	DR	LOCAL	61	489	25	12,225	909	Uncoated Chip		\$2.50	\$3,361.88
96792	1114	1130		COBLE	DR	LOCAL	61	438	25	10,950	909	Uncoated Chip		\$2.50	\$3,011.25
94947	1000	1048		COBLE	ST	LOCAL		800	30	24,000	635	Uncoated Chip		\$2.50	\$6,600.00
97010	1300	1304		COBLE	DR	LOCAL	56	292	30	8,760		Uncoated Chip		\$2.50	\$2,409.00
95730	1200	1208		COBLE	DR	LOCAL	64	346	30	10,380		Uncoated Chip		\$2.50	\$2,854.50
94667	900	930		COBLE	ST	LOCAL		469	35	16,415		Uncoated Chip		\$2.50	\$4,514.13
94710	100	128		COBLE	ST	LOCAL		294	35	10,290		Uncoated Chip		\$2.50	\$2,829.75
94712	500	532		COBLE	ST	LOCAL		461	30	13,830		Uncoated Chip		\$2.50	\$3,803.25
94811	300	330		COBLE	ST	LOCAL		428	30	12,840		Uncoated Chip		\$2.50	\$3,531.00
94812	600	630		COBLE	ST	LOCAL		463	30	13,890		Uncoated Chip		\$2.50	\$3,819.75
94869	400	430		COBLE	ST	LOCAL		464	30	13,920		Uncoated Chip		\$2.50	\$3,828.00
95069	200	230		COBLE	ST	LOCAL		495	35	17,325		Uncoated Chip		\$2.50	\$4,764.38
95107	700	730		COBLE	ST	LOCAL		460	30	13,800		Uncoated Chip		\$2.50	\$3,795.00
95727	1306	1330		COBLE	DR	LOCAL		814	30	24,420		Uncoated Chip		\$2.50	\$6,715.50
													Total:	\$55,837.38	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
95115	1100	1140		COFFEE	DR	LOCAL		2460	30	73,800		Coated Chip		\$2.95	\$23,948.10
													Total:	\$23,948.10	
95510	800	898		COLLEGE	AVE	LOCAL	66	366	30	10,980	4,698	Crack Seal		\$0.75	\$905.85
95508	600	698		COLLEGE	AVE	LOCAL	64	352	30	10,560	3,856	Uncoated Chip		\$2.50	\$2,904.00
95512	700	798		COLLEGE	AVE	LOCAL	64	359	35	12,565	3,446	Uncoated Chip		\$2.50	\$3,455.38
95509	900	998		COLLEGE	AVE	LOCAL	71	351	30	10,530		Crack Seal		\$0.75	\$868.73
95506	1200	1298		COLLEGE	AVE	LOCAL		502	30	15,060		Crack Seal		\$0.75	\$1,242.45
95507	1000	1098		COLLEGE	AVE	LOCAL		359	30	10,770		Crack Seal		\$0.75	\$888.53
95513	500	598		COLLEGE	AVE	LOCAL		717	30	21,510		Crack Seal		\$0.75	\$1,774.58
													Total:	\$12,039.50	
95404	200	222		CONCORD	ST	LOCAL		974	35	34,090		Uncoated Chip		\$2.50	\$9,374.75
													Total:	\$9,374.75	
96300	1108	1118		COOLEY	DR	LOCAL	42	712	30	21,360		Uncoated Chip		\$2.50	\$5,874.00
94845	1200	1224		COOLEY	DR	LOCAL		841	25	21,025		Uncoated Chip		\$2.50	\$5,781.88
94860	1400	1432		COOLEY	DR	LOCAL		1145	30	34,350		Uncoated Chip		\$2.50	\$9,446.25
94930	1300	1318		COOLEY	DR	LOCAL		670	25	16,750		Uncoated Chip		\$2.50	\$4,606.25
94960	1500	1506		COOLEY	DR	LOCAL		343	25	8,575		Uncoated Chip		\$2.50	\$2,358.13
													Total:	\$28,066.50	
94779	800	898 E		COOLIDGE	ST	LOCAL		280	15	4,200		Uncoated Chip		\$2.50	\$1,155.00
95020	500	528 W		COOLIDGE	ST	LOCAL		379	35	13,265		Uncoated Chip		\$2.50	\$3,647.88
95559	100	120 W		COOLIDGE	ST	LOCAL		655	35	22,925		Uncoated Chip		\$2.50	\$6,304.38
95571	400	428 W		COOLIDGE	ST	LOCAL		655	30	19,650		Uncoated Chip		\$2.50	\$5,403.75
95650	100	128 E		COOLIDGE	ST	LOCAL		603	35	21,105		Uncoated Chip		\$2.50	\$5,803.88
													Total:	\$22,314.88	
94853	1000	1058		CORONADO	CIR	LOCAL		517	130	67,210		Uncoated Chip		\$2.50	\$18,482.75
													Total:	\$18,482.75	
95433	201	215		COTTONWOOD	ST	LOCAL	41	549	35	19,215		Uncoated Chip		\$2.50	\$5,284.13
96756	217	225		COTTONWOOD	ST	LOCAL	41	274	35	9,590		Uncoated Chip		\$2.50	\$2,637.25
95426	101	123		COTTONWOOD	ST	LOCAL	55	959	45	43,155		Uncoated Chip		\$2.50	\$11,867.63
													Total:	\$19,789.00	
94788	900	908		COUNTRY CLUB	RD	LOCAL		192	25	4,800		Coated Chip		\$2.95	\$1,557.60
94939	802	812		COUNTRY CLUB	RD	LOCAL		557	25	13,925		Coated Chip		\$2.95	\$4,518.66
95711	700	798		COUNTRY CLUB	RD	LOCAL		131	25	3,275		Coated Chip		\$2.95	\$1,062.74
													Total:	\$7,139.00	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
94730	500	528		CROCKETT	ST	LOCAL		555	30	16,650		Uncoated Chip		\$2.50	\$4,578.75
													Total:	\$4,578.75	
95814	400	406		CYPRESS	ST	LOCAL		261	35	9,135		Uncoated Chip		\$2.50	\$2,512.13
													Total:	\$2,512.13	
95844	300	312		DALLAS	ST	LOCAL		618	30	18,540		Uncoated Chip		\$2.50	\$5,098.50
													Total:	\$5,098.50	
94744	100	130		DAVENPORT	ST	LOCAL		784	30	23,520		Uncoated Chip		\$2.50	\$6,468.00
95860	200	206		DAVENPORT	ST	LOCAL		283	30	8,490		Uncoated Chip		\$2.50	\$2,334.75
96981	208	214		DAVENPORT	ST	LOCAL		145	30	4,350		Uncoated Chip		\$2.50	\$1,196.25
													Total:	\$9,999.00	
95726	1300	1312		DAVIS	DR	LOCAL		409	30	12,270		Uncoated Chip		\$2.50	\$3,374.25
97013	1314	1330		DAVIS	DR	LOCAL		463	30	13,890		Uncoated Chip		\$2.50	\$3,819.75
													Total:	\$7,194.00	
95011	400	430		DEAHL	ST	LOCAL	53	460	35	16,100	4,099	Coated Chip		\$2.95	\$5,224.45
94842	300	330		DEAHL	ST	LOCAL	50	427	30	12,810	2,732	Coated Chip		\$2.95	\$4,156.85
95059	800	830		DEAHL	ST	LOCAL	35	467	35	16,345	1,938	Coated Chip		\$2.95	\$5,303.95
94862	700	730		DEAHL	ST	LOCAL	42	453	30	13,590		Coated Chip		\$2.95	\$4,409.96
95027	600	630		DEAHL	ST	LOCAL	47	465	40	18,600		Coated Chip		\$2.95	\$6,035.70
94668	500	532		DEAHL	ST	LOCAL	52	470	40	18,800		Coated Chip		\$2.95	\$6,100.60
94976	900	930		DEAHL	ST	LOCAL	55	481	30	14,430		Coated Chip		\$2.95	\$4,682.54
94666	200	230		DEAHL	ST	LOCAL		490	30	14,700		Uncoated Chip		\$2.50	\$4,042.50
94980	100	128		DEAHL	ST	LOCAL		296	35	10,360		Uncoated Chip		\$2.50	\$2,849.00
													Total:	\$42,805.54	
95136	1200	1328		DEL CORONADO	WAY	LOCAL		540	65	35,100		Uncoated Chip		\$2.50	\$9,652.50
													Total:	\$9,652.50	
94816	400	430		DELAWARE	ST	LOCAL	51	455	35	15,925		Uncoated Chip		\$2.50	\$4,379.38
95032	700	724		DELAWARE	ST	LOCAL	54	456	35	15,960		Uncoated Chip		\$2.50	\$4,389.00
94986	500	532		DELAWARE	ST	LOCAL	56	448	35	15,680		Uncoated Chip		\$2.50	\$4,312.00
94904	600	630		DELAWARE	ST	LOCAL	63	438	35	15,330		Uncoated Chip		\$2.50	\$4,215.75
													Total:	\$17,296.13	
94973	200	298		DENTON	ST	LOCAL		361	30	10,830		Uncoated Chip		\$2.50	\$2,978.25
													Total:	\$2,978.25	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
95249	700	728		DERR	ST	LOCAL		646	30	19,380		Uncoated Chip		\$2.50	\$5,329.50
95251	810	834		DERR	ST	LOCAL		920	30	27,600		Uncoated Chip		\$2.50	\$7,590.00
95263	900	906		DERR	ST	LOCAL		296	30	8,880		Uncoated Chip		\$2.50	\$2,442.00
Total:														\$15,361.50	
95694	1010	1010		DILLARD	DR	LOCAL		136	30	4,080		Uncoated Chip		\$2.50	\$1,122.00
95695	1012	1020		DILLARD	DR	LOCAL		333	30	9,990		Uncoated Chip		\$2.50	\$2,747.25
95696	1000	1008		DILLARD	DR	LOCAL		206	30	6,180		Uncoated Chip		\$2.50	\$1,699.50
Total:														\$5,568.75	
94809	900	930		DIXON	ST	LOCAL		457	35	15,995		Uncoated Chip		\$2.50	\$4,398.63
95079	700	730		DIXON	ST	LOCAL		455	30	13,650		Uncoated Chip		\$2.50	\$3,753.75
95108	800	830		DIXON	ST	LOCAL		471	35	16,485		Uncoated Chip		\$2.50	\$4,533.38
Total:														\$12,685.75	
95819	400	406		DOGWOOD	ST	LOCAL		225	35	7,875		Uncoated Chip		\$2.50	\$2,165.63
Total:														\$2,165.63	
95374	501	513		DOLOMITA	ST	LOCAL	38	392	35	13,720		Mill & Overlay		\$15.00	\$67,914.00
95375	401	409		DOLOMITA	ST	LOCAL	43	346	45	15,570		Uncoated Chip		\$2.50	\$4,281.75
95376	301	319		DOLOMITA	ST	LOCAL	44	698	40	27,920		Uncoated Chip		\$2.50	\$7,678.00
95378	201	213		DOLOMITA	ST	LOCAL	51	488	40	19,520		Uncoated Chip		\$2.50	\$5,368.00
95379	101	105		DOLOMITA	ST	LOCAL		246	40	9,840		Uncoated Chip		\$2.50	\$2,706.00
Total:														\$87,947.75	
95002	200	220		ELISE	ST	LOCAL		338	35	11,830		Uncoated Chip		\$2.50	\$3,253.25
95872	100	148		ELISE	ST	LOCAL		281	25	7,025		Uncoated Chip		\$2.50	\$1,931.88
Total:														\$5,185.13	
95427	101	131		ELM	ST	LOCAL		875	35	30,625		Uncoated Chip		\$2.50	\$8,421.88
Total:														\$8,421.88	
94754	940	998		ELMORE	ST	LOCAL		1473	25	36,825		Coated Chip		\$2.95	\$11,949.71
95692	1016	1042		ELMORE	ST	LOCAL		834	30	25,020		Coated Chip		\$2.95	\$8,118.99
95693	1102	1142		ELMORE	ST	LOCAL		2467	30	74,010		Coated Chip		\$2.95	\$24,016.25
96955	1000	1014		ELMORE	ST	LOCAL		548	25	13,700		Coated Chip		\$2.95	\$4,445.65
97235	1044	1044		ELMORE	ST	LOCAL		363	25	9,075		Coated Chip		\$2.95	\$2,944.84
Total:														\$51,475.44	
94943	400	530		EMPIRE	ST	LOCAL		1132	30	33,960		Uncoated Chip		\$2.50	\$9,339.00
Total:														\$9,339.00	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
95365	503	507		ESTIRENO	ST	LOCAL		361	30	10,830		Uncoated Chip		\$2.50	\$2,978.25
95368	301	321		ESTIRENO	ST	LOCAL		778	30	23,340		Uncoated Chip		\$2.50	\$6,418.50
95369	201	213		ESTIRENO	ST	LOCAL		432	40	17,280		Uncoated Chip		\$2.50	\$4,752.00
95370	101	107		ESTIRENO	ST	LOCAL		292	40	11,680		Uncoated Chip		\$2.50	\$3,212.00
													Total:	\$17,360.75	
95465	1100	1114		EVEREST	ST	LOCAL		534	30	16,020		Uncoated Chip		\$2.50	\$4,405.50
													Total:	\$4,405.50	
95781	900	910		EVERGREEN	ST	LOCAL	38	290	35	10,150		Mill & Overlay		\$15.00	\$50,242.50
95812	800	810		EVERGREEN	ST	LOCAL	40	313	35	10,955		Mill & Overlay		\$15.00	\$54,227.25
95803	1000	1008		EVERGREEN	ST	LOCAL	41	307	35	10,745		Mill & Overlay		\$15.00	\$53,187.75
95810	1200	1208		EVERGREEN	ST	LOCAL	42	307	35	10,745		Coated Chip		\$2.95	\$3,486.75
95854	1100	1108		EVERGREEN	ST	LOCAL	47	316	35	11,060		Coated Chip		\$2.95	\$3,588.97
96273	620	628		EVERGREEN	ST	LOCAL	48	342	35	11,970		Mill & Overlay		\$15.00	\$59,251.50
96274	672	680		EVERGREEN	ST	LOCAL	48	322	35	11,270		Mill & Overlay		\$15.00	\$55,786.50
96275	668	670		EVERGREEN	ST	LOCAL	48	1242	35	43,470		Mill & Overlay		\$15.00	\$215,176.50
97118	612	618		EVERGREEN	ST	LOCAL	48	343	30	10,290		Mill & Overlay		\$15.00	\$50,935.50
95146	1300	1318		EVERGREEN	ST	LOCAL		637	35	22,295		Coated Chip		\$2.95	\$7,234.73
95800	682	706		EVERGREEN	ST	LOCAL		301	35	10,535		Mill & Overlay		\$15.00	\$52,148.25
95841	630	664		EVERGREEN	ST	LOCAL		1027	30	30,810		Mill & Overlay		\$15.00	\$152,509.50
													Total:	\$757,775.70	
95420	118	142		FAIRVIEW	ST	LOCAL		1073	30	32,190		Uncoated Chip		\$2.50	\$8,852.25
96781	100	116		FAIRVIEW	ST	LOCAL		737	30	22,110		Uncoated Chip		\$2.50	\$6,080.25
													Total:	\$14,932.50	
94873	700	724		FERGUSON	ST	LOCAL		591	30	17,730		Uncoated Chip		\$2.50	\$4,875.75
													Total:	\$4,875.75	
94866	1200	1210		FINGER	ST	LOCAL	62	241	30	7,230		Uncoated Chip		\$2.50	\$1,988.25
94708	1300	1320		FINGER	ST	LOCAL		697	25	17,425		Uncoated Chip		\$2.50	\$4,791.88
95891	1400	1420		FINGER	ST	LOCAL		396	25	9,900		Uncoated Chip		\$2.50	\$2,722.50
													Total:	\$9,502.63	
95732	1300	1330		FRANCIS	ST	LOCAL		855	25	21,375		Uncoated Chip		\$2.50	\$17,634.38
													Total:	\$17,634.38	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
94690	400	428		FRANKLIN	ST	LOCAL		740	30	22,200		Uncoated Chip		\$2.50	\$6,105.00
94832	900	930		FRANKLIN	ST	LOCAL		336	35	11,760		Coated Chip		\$2.95	\$3,816.12
95089	500	528		FRANKLIN	ST	LOCAL		381	30	11,430		Coated Chip		\$2.95	\$3,709.04
95118	600	628		FRANKLIN	ST	LOCAL		357	30	10,710		Coated Chip		\$2.95	\$3,475.40
95490	1000	1030		FRANKLIN	ST	LOCAL		363	30	10,890		Uncoated Chip		\$2.50	\$2,994.75
													Total:	\$20,100.30	
95007	100	148		FROMA	ST	LOCAL		1148	1148	1,317,904		Uncoated Chip		\$2.50	\$362,423.60
													Total:	\$362,423.60	
95371	101	111		FRONTERA	ST	LOCAL		333	333	110,889		Uncoated Chip		\$2.50	\$30,494.48
95373	301	311		FRONTERA	ST	LOCAL		374	25	9,350		Uncoated Chip		\$2.50	\$2,571.25
													Total:	\$33,065.73	
95775	400	410		GALAHAD	ST	LOCAL	58	300	35	10,500	1,708	Uncoated Chip		\$2.50	\$2,887.50
95077	100	120		GALAHAD	ST	LOCAL	52	776	35	27,160		Coated Chip		\$2.95	\$8,813.42
95768	200	210		GALAHAD	ST	LOCAL	53	303	35	10,605		Coated Chip		\$2.95	\$3,441.32
95786	300	310		GALAHAD	ST	LOCAL	55	304	35	10,640		Coated Chip		\$2.95	\$3,452.68
95143	600	610		GALAHAD	ST	LOCAL	64	292	35	10,220		Uncoated Chip		\$2.50	\$2,810.50
95809	500	510		GALAHAD	ST	LOCAL	66	295	35	10,325		Crack Seal		\$0.75	\$851.81
													Total:	\$22,257.24	
95856	100	118		GARDNER	ST	LOCAL	56	800	30	24,000	2,060	Uncoated Chip		\$2.50	\$6,600.00
95855	200	218		GARDNER	ST	LOCAL	48	1059	30	31,770		Uncoated Chip		\$2.50	\$8,736.75
96928	600	602		GARDNER	ST	LOCAL	54	295	35	10,325		Uncoated Chip		\$2.50	\$2,839.38
96930	606	610		GARDNER	ST	LOCAL	54	152	35	5,320		Uncoated Chip		\$2.50	\$1,463.00
94984	500	516		GARDNER	ST	LOCAL	55	172	30	5,160		Uncoated Chip		\$2.50	\$1,419.00
94804	400	418		GARDNER	ST	LOCAL	60	524	30	15,720		Uncoated Chip		\$2.50	\$4,323.00
95857	300	316		GARDNER	ST	LOCAL	63	454	30	13,620		Uncoated Chip		\$2.50	\$3,745.50
													Total:	\$29,126.63	
95838	300	312		GARRETT	ST	LOCAL	50	403	35	14,105		Uncoated Chip		\$2.50	\$3,878.88
96799	314	320		GARRETT	ST	LOCAL	50	318	35	11,130		Uncoated Chip		\$2.50	\$3,060.75
95798	200	238		GARRETT	ST	LOCAL	58	1109	35	38,815		Uncoated Chip		\$2.50	\$10,674.13
95793	400	404		GARRETT	ST	LOCAL		159	35	5,565		Uncoated Chip		\$2.50	\$1,530.38
95852	108	116		GARRETT	ST	LOCAL		303	35	10,605		Uncoated Chip		\$2.50	\$2,916.38
96795	100	106		GARRETT	ST	LOCAL		306	35	10,710		Uncoated Chip		\$2.50	\$2,945.25
96796	118	124		GARRETT	ST	LOCAL		295	35	10,325		Uncoated Chip		\$2.50	\$2,839.38
													Total:	\$27,845.13	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
95698	1108	1114		GATEWAY	CIR	LOCAL	53	651	30	19,530		Coated Chip		\$2.95	\$6,337.49
94938	1116	1124		GATEWAY	CIR	LOCAL		261	25	6,525		Coated Chip		\$2.95	\$2,117.36
													Total:	\$8,454.85	
95799	1500	1524		GAWAIN	ST	LOCAL		689	30	20,670		Uncoated Chip		\$2.50	\$5,684.25
													Total:	\$5,684.25	
94692	700	898 E		GRAND	ST	LOCAL		1377	15	20,655		None		\$0.00	\$0.00
95090	500	598 W		GRAND	ST	LOCAL		371	60	22,260		Coated Chip		\$2.95	\$7,223.37
95556	200	218 W		GRAND	ST	LOCAL		661	60	39,660		Coated Chip		\$2.95	\$12,869.67
95586	300	328 W		GRAND	ST	LOCAL		651	60	39,060		Coated Chip		\$2.95	\$12,674.97
95643	100	128 E		GRAND	ST	LOCAL		376	60	22,560		Uncoated Chip		\$2.50	\$6,204.00
													Total:	\$38,972.01	
94693	200	398		GRAVEL PIT	RD	LOCAL		811	35	28,385		Uncoated Chip		\$2.50	\$7,805.88
94927	401	499		GRAVEL PIT	RD	LOCAL		300	30	9,000		Uncoated Chip		\$2.50	\$2,475.00
													Total:	\$10,280.88	
95720	510	530		GREEN	ST	LOCAL		188	20	3,760		Uncoated Chip		\$2.50	\$1,034.00
													Total:	\$1,034.00	
95861	1000	1020		HACKBERRY	ST	LOCAL		538	25	13,450		Coated Chip		\$2.95	\$4,364.53
95862	1100	1198		HACKBERRY	ST	LOCAL		356	35	12,460		Reconstruct		\$49.00	\$201,478.20
													Total:	\$205,842.73	
95071	1308	1338		HAGGARD	ST	LOCAL		982	25	24,550		Uncoated Chip		\$2.50	\$6,751.25
97007	1200	1202		HAGGARD	ST	LOCAL		828	30	24,840		Uncoated Chip		\$2.50	\$6,831.00
													Total:	\$13,582.25	
94899	926	934		HARRINGTON	ST	LOCAL	47	296	30	8,880		Coated Chip		\$2.95	\$2,881.56
95689	936	942		HARRINGTON	ST	LOCAL	48	270	30	8,100		Coated Chip		\$2.95	\$2,628.45
95690	900	924		HARRINGTON	ST	LOCAL	50	888	30	26,640		Coated Chip		\$2.95	\$8,644.68
95687	1006	1018		HARRINGTON	ST	LOCAL	52	572	30	17,160		Coated Chip		\$2.95	\$5,568.42
95688	944	1002		HARRINGTON	ST	LOCAL		486	30	14,580		Coated Chip		\$2.95	\$4,731.21
													Total:	\$24,454.32	
94750	1000	1030		HARRISON	ST	LOCAL		358	30	10,740		Uncoated Chip		\$2.50	\$2,953.50
95493	900	930		HARRISON	ST	LOCAL		331	30	9,930		Uncoated Chip		\$2.50	\$2,730.75
													Total:	\$5,684.25	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
95597	200	228 S	HARVEY	ST	LOCAL	69	306	30	9,180	6,940	Crack Seal			\$0.75	\$757.35
94922	520	528 S	HARVEY	ST	LOCAL		422	30	12,660	6,773	Uncoated Chip			\$2.50	\$3,481.50
94911	400	430 N	HARVEY	ST	LOCAL	65	458	30	13,740	6,045	Uncoated Chip			\$2.50	\$3,778.50
94797	900	930 N	HARVEY	ST	LOCAL	57	452	30	13,560	4,940	Uncoated Chip			\$2.50	\$3,729.00
95121	800	830 N	HARVEY	ST	LOCAL	59	458	30	13,740		Uncoated Chip			\$2.50	\$3,778.50
94961	600	630 N	HARVEY	ST	LOCAL	61	459	30	13,770		Uncoated Chip			\$2.50	\$3,786.75
95132	100	128 N	HARVEY	ST	LOCAL	61	300	30	9,000		Uncoated Chip			\$2.50	\$2,475.00
94753	500	532 N	HARVEY	ST	LOCAL	62	471	30	14,130		Uncoated Chip			\$2.50	\$3,885.75
94868	200	230 N	HARVEY	ST	LOCAL	63	458	30	13,740		Uncoated Chip			\$2.50	\$3,778.50
94794	300	328 S	HARVEY	ST	LOCAL	64	226	30	6,780		Uncoated Chip			\$2.50	\$1,864.50
95063	700	730 N	HARVEY	ST	LOCAL	64	463	30	13,890		Uncoated Chip			\$2.50	\$3,819.75
95070	300	330 N	HARVEY	ST	LOCAL	64	433	30	12,990		Uncoated Chip			\$2.50	\$3,572.25
95592	100	128 S	HARVEY	ST	LOCAL	64	360	30	10,800		Uncoated Chip			\$2.50	\$2,970.00
													Total:	\$41,677.35	
94762	1200	1226	HAZELWOOD	AVE	LOCAL		888	25	22,200		Uncoated Chip			\$2.50	\$6,105.00
94901	1300	1314	HAZELWOOD	AVE	LOCAL		586	25	14,650		Uncoated Chip			\$2.50	\$4,028.75
95009	1400	1424	HAZELWOOD	AVE	LOCAL		643	25	16,075		Uncoated Chip			\$2.50	\$4,420.63
													Total:	\$14,554.38	
95785	1500	1524	HECTOR	ST	LOCAL		682	30	20,460		Uncoated Chip			\$2.50	\$5,626.50
													Total:	\$5,626.50	
94724	400	430 N	HEDGEKOKE	ST	LOCAL	64	464	30	13,920	5,861	Coated Chip			\$2.95	\$4,517.04
95610	200	228 S	HEDGEKOKE	ST	LOCAL		304	30	9,120	4,198	Coated Chip			\$2.95	\$2,959.44
94838	800	830 N	HEDGEKOKE	ST	LOCAL	65	461	30	13,830	4,073	Coated Chip			\$2.95	\$4,487.84
95602	300	328 S	HEDGEKOKE	ST	LOCAL	66	356	30	10,680	4,010	Crack Seal			\$0.75	\$881.10
95087	500	532 N	HEDGEKOKE	ST	LOCAL	62	463	30	13,890	3,986	Coated Chip			\$2.95	\$4,507.31
94896	900	930 N	HEDGEKOKE	ST	LOCAL	64	477	30	14,310	3,982	Coated Chip			\$2.95	\$4,643.60
95608	600	698 S	HEDGEKOKE	ST	LOCAL		360	30	10,800	3,951	Coated Chip			\$2.95	\$3,504.60
95544	800	828 S	HEDGEKOKE	ST	LOCAL	64	352	30	10,560	3,939	Coated Chip			\$2.95	\$3,426.72
94755	700	730 N	HEDGEKOKE	ST	LOCAL	59	454	30	13,620	3,827	Coated Chip			\$2.95	\$4,419.69
94953	200	230 N	HEDGEKOKE	ST	LOCAL	57	495	30	14,850		Coated Chip			\$2.95	\$4,818.83
94932	600	630 N	HEDGEKOKE	ST	LOCAL	58	465	30	13,950		Coated Chip			\$2.95	\$4,526.78
94720	300	330 N	HEDGEKOKE	ST	LOCAL	61	423	30	12,690		Coated Chip			\$2.95	\$4,117.91
95594	400	428 S	HEDGEKOKE	ST	LOCAL	61	380	30	11,400		Coated Chip			\$2.95	\$3,699.30
94865	100	128 N	HEDGEKOKE	ST	LOCAL	65	293	30	8,790		Coated Chip			\$2.95	\$2,852.36
95591	100	128 S	HEDGEKOKE	ST	LOCAL	65	358	30	10,740		Coated Chip			\$2.95	\$3,485.13
95546	700	728 S	HEDGEKOKE	ST	LOCAL	69	369	30	11,070		Crack Seal			\$0.75	\$913.28
95117	900	928 S	HEDGEKOKE	ST	LOCAL	72	350	30	10,500		Crack Seal			\$0.75	\$866.25
95606	500	528 S	HEDGEKOKE	ST	LOCAL		367	30	11,010		Coated Chip			\$2.95	\$3,572.75
													Total:	\$62,199.89	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
95486	1300	1310		HEMLOCK	ST	LOCAL	41	345	30	10,350		Coated Chip		\$2.95	\$3,358.58
95467	1700	1710		HEMLOCK	ST	LOCAL	42	828	35	28,980		Coated Chip		\$2.95	\$9,404.01
95484	1200	1210		HEMLOCK	ST	LOCAL	45	357	30	10,710		Coated Chip		\$2.95	\$3,475.40
95491	1000	1020		HEMLOCK	ST	LOCAL	50	360	30	10,800		Coated Chip		\$2.95	\$3,504.60
95476	1400	1408		HEMLOCK	ST	LOCAL	54	618	25	15,450		Coated Chip		\$2.95	\$5,013.53
95475	1410	1420		HEMLOCK	ST	LOCAL	57	357	25	8,925		Coated Chip		\$2.95	\$2,896.16
95457	2100	2128		HEMLOCK	ST	LOCAL		856	45	38,520		Coated Chip		\$2.95	\$12,499.74
95459	2000	2012		HEMLOCK	ST	LOCAL		440	30	13,200		Coated Chip		\$2.95	\$4,283.40
95485	1100	1120		HEMLOCK	ST	LOCAL		179	35	6,265		Coated Chip		\$2.95	\$2,032.99
95492	800	824		HEMLOCK	ST	LOCAL		357	35	12,495		Coated Chip		\$2.95	\$4,054.63
95494	900	928		HEMLOCK	ST	LOCAL		360	30	10,800		Coated Chip		\$2.95	\$3,504.60
95495	600	648		HEMLOCK	ST	LOCAL		351	40	14,040		Coated Chip		\$2.95	\$4,555.98
95496	702	710		HEMLOCK	ST	LOCAL		81	30	2,430		Coated Chip		\$2.95	\$788.54
													Total:	\$59,372.14	
94949	1400	1410		HERBST	ST	LOCAL		447	25	11,175		Uncoated Chip		\$2.50	\$3,073.13
													Total:	\$3,073.13	
95435	201	225		HICKORY	ST	LOCAL		826	40	33,040		Uncoated Chip		\$2.50	\$9,086.00
													Total:	\$9,086.00	
95884	101	111		HILL	ST	LOCAL		380	45	17,100		Uncoated Chip		\$2.50	\$4,702.50
													Total:	\$4,702.50	
95253	700	724		HOBBY	ST	LOCAL		634	35	22,190		Uncoated Chip		\$2.50	\$6,102.25
													Total:	\$6,102.25	
95708	800	814		HOME	RD	LOCAL		678	25	16,950		Uncoated Chip		\$2.50	\$4,661.25
													Total:	\$4,661.25	
94933	2	98		HOUSE	ST	LOCAL		667	20	13,340		Uncoated Chip		\$2.50	\$3,668.50
													Total:	\$3,668.50	
94978	300	316		HOUSTON	ST	LOCAL		447	30	13,410		Coated Chip		\$2.95	\$4,351.55
95010	200	210		HOUSTON	ST	LOCAL		442	30	13,260		Coated Chip		\$2.95	\$4,302.87
95811	400	416		HOUSTON	ST	LOCAL		522	30	15,660		Coated Chip		\$2.95	\$5,081.67
95816	100	120		HOUSTON	ST	LOCAL		223	35	7,805		Coated Chip		\$2.95	\$2,532.72
													Total:	\$16,268.81	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
95453	2300	2330		HUBER	AVE	LOCAL	41	600	25	15,000		Coated Chip		\$2.95	\$4,867.50
95452	2100	2128		HUBER	AVE	LOCAL	44	881	20	17,620		Coated Chip		\$2.95	\$5,717.69
95451	2200	2298		HUBER	AVE	LOCAL		1035	30	31,050		Coated Chip		\$2.95	\$10,075.73
95454	2008	2098		HUBER	AVE	LOCAL		808	20	16,160		Coated Chip		\$2.95	\$5,243.92
													Total:	\$25,904.84	
94675	900	940		ILLINOIS	ST	LOCAL		692	25	17,300		Uncoated Chip		\$2.50	\$4,757.50
95474	1000	1028		ILLINOIS	ST	LOCAL		967	25	24,175		Uncoated Chip		\$2.50	\$6,648.13
													Total:	\$11,405.63	
94920	100	124		INA	ST	LOCAL		817	30	24,510		Uncoated Chip		\$2.50	\$6,740.25
													Total:	\$6,740.25	
95468	1102	1118		INDIANA	ST	LOCAL		253	35	8,855		Uncoated Chip		\$2.50	\$2,435.13
95469	1200	1220		INDIANA	ST	LOCAL		560	35	19,600		Uncoated Chip		\$2.50	\$5,390.00
													Total:	\$7,825.13	
96334	100	198		INGLEWOOD	ST	LOCAL		304	30	9,120		Uncoated Chip		\$2.50	\$2,508.00
													Total:	\$2,508.00	
95409	200	228		INVERNESS	ST	LOCAL	40	1236	35	43,260		Coated Chip		\$2.95	\$14,037.87
95408	300	324		INVERNESS	ST	LOCAL		104	35	3,640		Coated Chip		\$2.95	\$1,181.18
96401	100	102		INVERNESS	ST	LOCAL		164	30	4,920		Coated Chip		\$2.95	\$1,596.54
96696	104	106		INVERNESS	ST	LOCAL		317	30	9,510		Coated Chip		\$2.95	\$3,086.00
													Total:	\$19,901.59	
94703	900	930		JACKSON	ST	LOCAL		332	30	9,960		Uncoated Chip		\$2.50	\$2,739.00
94773	200	298		JACKSON	ST	LOCAL		114	30	3,420		Uncoated Chip		\$2.50	\$940.50
94791	1000	1030		JACKSON	ST	LOCAL		372	30	11,160		Uncoated Chip		\$2.50	\$3,069.00
94997	500	528		JACKSON	ST	LOCAL		374	35	13,090		Uncoated Chip		\$2.50	\$3,599.75
95119	600	628		JACKSON	ST	LOCAL		360	30	10,800		Uncoated Chip		\$2.50	\$2,970.00
95502	1100	1230		JACKSON	ST	LOCAL		720	30	21,600		Uncoated Chip		\$2.50	\$5,940.00
95521	700	728		JACKSON	ST	LOCAL		620	30	18,600		Uncoated Chip		\$2.50	\$5,115.00
95529	300	328		JACKSON	ST	LOCAL		661	30	19,830		Uncoated Chip		\$2.50	\$5,453.25
													Total:	\$29,826.50	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
95086	500	528	W	JEFFERSON	ST	LOCAL	74	384	30	11,520		Crack Seal		\$0.75	\$950.40
94928	900	1000	E	JEFFERSON	ST	LOCAL		666	20	13,320		Crack Seal		\$0.75	\$1,098.90
95567	100	128	W	JEFFERSON	ST	LOCAL		659	30	19,770		Uncoated Chip		\$2.50	\$5,436.75
95570	300	328	W	JEFFERSON	ST	LOCAL		656	30	19,680		Uncoated Chip		\$2.50	\$5,412.00
95621	300	330	E	JEFFERSON	ST	LOCAL		251	45	11,295		Uncoated Chip		\$2.50	\$3,106.13
95647	200	228	E	JEFFERSON	ST	LOCAL		660	30	19,800		Uncoated Chip		\$2.50	\$5,445.00
													Total:	\$21,449.18	
95128	1400	1420		JENNINGS	ST	LOCAL		669	30	20,070		Uncoated Chip		\$2.50	\$5,519.25
													Total:	\$5,519.25	
94940	1200	1220		JIM HALL	ST	LOCAL		360	20	7,200		Coated Chip		\$2.95	\$2,336.40
95725	1000	1068		JIM HALL	ST	LOCAL		191	30	5,730		Coated Chip		\$2.95	\$1,859.39
95882	1300	1320		JIM HALL	ST	LOCAL		334	25	8,350		Coated Chip		\$2.95	\$2,709.58
													Total:	\$6,905.36	
95683	1004	1016		JOHNSON	ST	LOCAL		333	25	8,325		Uncoated Chip		\$2.50	\$2,289.38
96947	1000	1002		JOHNSON	ST	LOCAL		158	25	3,950		Uncoated Chip		\$2.50	\$1,086.25
													Total:	\$3,375.63	
94702	1300	1320		JOLLY	ST	LOCAL		569	25	14,225		Uncoated Chip		\$2.50	\$3,911.88
													Total:	\$3,911.88	
94792	800	824		JUNIPER	ST	LOCAL		353	25	8,825		Uncoated Chip		\$2.50	\$2,426.88
95478	1200	1210		JUNIPER	ST	LOCAL		357	35	12,495		Uncoated Chip		\$2.50	\$3,436.13
95483	1000	1020		JUNIPER	ST	LOCAL		363	30	10,890		Uncoated Chip		\$2.50	\$2,994.75
95487	900	928		JUNIPER	ST	LOCAL		357	35	12,495		Uncoated Chip		\$2.50	\$3,436.13
95489	1300	1310		JUNIPER	ST	LOCAL		360	35	12,600		Uncoated Chip		\$2.50	\$3,465.00
													Total:	\$15,758.88	
95769	400	498		KAYE	ST	LOCAL		591	35	20,685		Coated Chip		\$2.95	\$6,712.28
95839	500	504		KAYE	ST	LOCAL		457	35	15,995		Coated Chip		\$2.95	\$5,190.38
95840	606	610		KAYE	ST	LOCAL		343	35	12,005		Coated Chip		\$2.95	\$3,895.62
													Total:	\$15,798.28	
95685	1000	1020		KEITH	ST	LOCAL		715	30	21,450		Uncoated Chip		\$2.50	\$5,898.75
													Total:	\$5,898.75	
97285	100	124		KIEKBUSCH	ST	LOCAL		825	30	24,750		Uncoated Chip		\$2.50	\$6,806.25
97286	200	230		KIEKBUSCH	ST	LOCAL		735	35	25,725		Uncoated Chip		\$2.50	\$7,074.38
													Total:	\$7,074.38	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
95321	104	120		LAKEVIEW	ST			534	35	18,690		Mill & Overlay		\$15.00	\$92,515.50
													Total:	\$92,515.50	
95818	1400	1428		LANCELOT	ST	LOCAL	59	952	35	33,320	705	Coated Chip		\$2.95	\$10,812.34
95835	1500	1518		LANCELOT	ST	LOCAL		697	35	24,395		Coated Chip		\$2.95	\$7,916.18
96970	1520	1530		LANCELOT	ST	LOCAL		674	35	23,590		Coated Chip		\$2.95	\$7,654.96
													Total:	\$26,383.47	
96335	100	198		LARAMIE	ST	LOCAL		122	35	4,270		Uncoated Chip		\$2.50	\$1,174.25
													Total:	\$1,174.25	
95703	800	824		LATIMER	ST	LOCAL		765	30	22,950		Uncoated Chip		\$2.50	\$6,311.25
95704	826	828		LATIMER	ST	LOCAL		242	25	6,050		Uncoated Chip		\$2.50	\$1,663.75
													Total:	\$7,975.00	
94849	500	528		LEE	ST	LOCAL		378	35	13,230		Uncoated Chip		\$2.50	\$3,638.25
94887	900	930		LEE	ST	LOCAL		339	35	11,865		Uncoated Chip		\$2.50	\$3,262.88
94993	400	428		LEE	ST	LOCAL		344	35	12,040		Uncoated Chip		\$2.50	\$3,311.00
95048	600	628		LEE	ST	LOCAL		360	35	12,600		Uncoated Chip		\$2.50	\$3,465.00
95479	1000	1030		LEE	ST	LOCAL		362	35	12,670		Uncoated Chip		\$2.50	\$3,484.25
95499	1200	1230		LEE	ST	LOCAL		719	35	25,165		Uncoated Chip		\$2.50	\$6,920.38
95517	700	728		LEE	ST	LOCAL		622	35	21,770		Uncoated Chip		\$2.50	\$5,986.75
													Total:	\$30,068.50	
95355	400	404		LINDEN	ST	LOCAL		309	35	10,815		Uncoated Chip		\$2.50	\$2,974.13
													Total:	\$2,974.13	
94732	1100	1120		LINDSEY	ST	LOCAL		507	30	15,210		Uncoated Chip		\$2.50	\$4,182.75
95740	1200	1226		LINDSEY	ST	LOCAL		972	25	24,300		Uncoated Chip		\$2.50	\$6,682.50
													Total:	\$10,865.25	
95458	2000	2012		LISTER	ST	LOCAL		426	35	14,910		Uncoated Chip		\$2.50	\$4,100.25
95460	201	219		LISTER	ST	LOCAL		427	30	12,810		Uncoated Chip		\$2.50	\$3,522.75
95461	1900	1910		LISTER	ST	LOCAL		770	35	26,950		Uncoated Chip		\$2.50	\$7,411.25
													Total:	\$15,034.25	
94818	400	498		LOCUST	ST	LOCAL		1192	30	35,760		Uncoated Chip		\$2.50	\$9,834.00
96258	600	900		LOCUST	ST	LOCAL		675	40	27,000		Uncoated Chip		\$2.50	\$7,425.00
													Total:	\$17,259.00	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
95345	200	214		LOMA LINDA	LN	LOCAL		708	35	24,780		Uncoated Chip		\$2.50	\$6,814.50
													Total:	\$6,814.50	
94697	900	1028		MADISON	ST	LOCAL		701	35	24,535		Uncoated Chip		\$2.50	\$6,747.13
94793	500	528		MADISON	ST	LOCAL		370	30	11,100		Uncoated Chip		\$2.50	\$3,052.50
95109	600	628		MADISON	ST	LOCAL		355	35	12,425		Uncoated Chip		\$2.50	\$3,416.88
95504	1100	1208		MADISON	ST	LOCAL		717	35	25,095		Uncoated Chip		\$2.50	\$6,901.13
95525	700	728		MADISON	ST	LOCAL		601	35	21,035		Uncoated Chip		\$2.50	\$5,784.63
95577	100	128		MADISON	ST	LOCAL		549	35	19,215		Uncoated Chip		\$2.50	\$5,284.13
95579	300	328		MADISON	ST	LOCAL		659	30	19,770		Uncoated Chip		\$2.50	\$5,436.75
													Total:	\$36,623.13	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
94999	700	730	N	MAIN	ST	LOCAL	30	460	65	29,900		Mill & Overlay		\$15.00	\$148,005.00
95747	900	940	N	MAIN	ST	LOCAL	39	478	65	31,070		Mill & Overlay		\$15.00	\$153,796.50
94962	800	830	N	MAIN	ST	LOCAL	45	460	65	29,900		Mill & Overlay		\$15.00	\$148,005.00
95760	700	730	S	MAIN	ST	LOCAL	56	428	40	17,120		Coated Chip		\$2.95	\$5,555.44
95603	500	528	S	MAIN	ST	LOCAL	57	367	65	23,855		Coated Chip		\$2.95	\$7,740.95
95600	100	128	S	MAIN	ST	LOCAL	58	359	65	23,335		Coated Chip		\$2.95	\$7,572.21
95752	1500	1598	S	MAIN	ST	LOCAL	58	699	65	45,435		Coated Chip		\$2.95	\$14,743.66
95756	1100	1120	S	MAIN	ST	LOCAL	58	412	40	16,480		Coated Chip		\$2.95	\$5,347.76
95759	800	830	S	MAIN	ST	LOCAL	58	423	40	16,920		Coated Chip		\$2.95	\$5,490.54
95753	1400	1420	S	MAIN	ST	LOCAL	59	275	65	17,875		Coated Chip		\$2.95	\$5,800.44
95100	600	630	N	MAIN	ST	LOCAL	60	457	65	29,705		Coated Chip		\$2.95	\$9,639.27
95611	400	428	S	MAIN	ST	LOCAL	60	385	65	25,025		Coated Chip		\$2.95	\$8,120.61
95755	1300	1348	S	MAIN	ST	LOCAL	60	798	60	47,880		Coated Chip		\$2.95	\$15,537.06
95078	100	128	N	MAIN	ST	LOCAL	61	301	65	19,565		Coated Chip		\$2.95	\$6,348.84
95590	300	328	S	MAIN	ST	LOCAL	61	357	65	23,205		Coated Chip		\$2.95	\$7,530.02
94807	200	230	N	MAIN	ST	LOCAL	62	486	65	31,590		Coated Chip		\$2.95	\$10,250.96
95091	400	430	N	MAIN	ST	LOCAL	62	453	65	29,445		Coated Chip		\$2.95	\$9,554.90
95133	500	532	N	MAIN	ST	LOCAL	62	472	65	30,680		Coated Chip		\$2.95	\$9,955.66
94714	1512	1528	N	MAIN	ST	LOCAL		947	65	61,555		Coated Chip		\$2.95	\$19,974.60
94768	300	334	N	MAIN	ST	LOCAL		430	65	27,950		Mill & Overlay		\$15.00	\$138,352.50
94799	1300	1338	N	MAIN	ST	LOCAL		720	65	46,800		Coated Chip		\$2.95	\$15,186.60
94822	1418	1426	N	MAIN	ST	LOCAL		120	65	7,800		Coated Chip		\$2.95	\$2,531.10
94839	1402	1416	N	MAIN	ST	LOCAL		135	65	8,775		Coated Chip		\$2.95	\$2,847.49
95046	1200	1214	N	MAIN	ST	LOCAL		150	65	9,750		Coated Chip		\$2.95	\$3,163.88
95096	1428	1502	N	MAIN	ST	LOCAL		574	65	37,310		Coated Chip		\$2.95	\$12,107.10
95598	200	228	S	MAIN	ST	LOCAL		300	65	19,500		Coated Chip		\$2.95	\$6,327.75
95746	1000	1048	N	MAIN	ST	LOCAL		324	65	21,060		Coated Chip		\$2.95	\$6,833.97
95750	1100	1120	N	MAIN	ST	LOCAL		268	65	17,420		Coated Chip		\$2.95	\$5,652.79
95754	1200	1208	S	MAIN	ST	LOCAL		247	40	9,880		Coated Chip		\$2.95	\$3,206.06
95758	900	918	S	MAIN	ST	LOCAL		217	40	8,680		Coated Chip		\$2.95	\$2,816.66
95911	1600	1628	N	MAIN	ST	LOCAL		1737	65	112,905		Coated Chip		\$2.95	\$36,637.67
96987	616	630	S	MAIN	ST	LOCAL		202	40	8,080		Coated Chip		\$2.95	\$2,621.96
													Total:	\$837,254.94	
95440	101	113		MAPLE	ST	LOCAL		704	35	24,640	1,035	Mill & Overlay		\$15.00	\$121,968.00
96758	119	125		MAPLE	ST	LOCAL		271	35	9,485	1,035	Mill & Overlay		\$15.00	\$46,950.75
95431	201	225		MAPLE	ST	LOCAL	29	825	40	33,000		Mill & Overlay		\$15.00	\$163,350.00
													Total:	\$332,268.75	
94715	1200	1298		MARCY	TRL	LOCAL		2430	70	170,100		Coated Chip		\$2.95	\$55,197.45
													Total:	\$55,197.45	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
95837	1400	1438		MARIGOLD	ST	LOCAL		449	35	15,715		Uncoated Chip		\$2.50	\$4,321.63
													Total:	\$4,321.63	
95878	100	198		MARTINEZ	PL	LOCAL		1314	20	26,280		None		\$0.00	\$0.00
													Total:	\$0.00	
95006	100	130		MARY	ST	LOCAL		657	20	13,140		Uncoated Chip		\$2.50	\$3,613.50
95008	2	98		MARY	ST	LOCAL		487	25	12,175		Uncoated Chip		\$2.50	\$3,348.13
													Total:	\$6,961.63	
95850	200	212		MCCARTHY	ST	LOCAL		444	35	15,540		Uncoated Chip		\$2.50	\$4,273.50
95851	300	302		MCCARTHY	ST	LOCAL		285	35	9,975		Uncoated Chip		\$2.50	\$2,743.13
96794	304	318		MCCARTHY	ST	LOCAL		286	35	10,010		Uncoated Chip		\$2.50	\$2,752.75
96797	214	220		MCCARTHY	ST	LOCAL		275	35	9,625		Uncoated Chip		\$2.50	\$2,646.88
													Total:	\$12,416.25	
95613	500	540 N		MCGEE	ST	LOCAL		313	35	10,955	5,181	Coated Chip		\$2.95	\$3,554.90
94917	300	324 N		MCGEE	ST	LOCAL	56	430	30	12,900	4,789	Coated Chip		\$2.95	\$4,186.05
94765	400	432 N		MCGEE	ST	LOCAL	58	456	30	13,680	4,675	Coated Chip		\$2.95	\$4,439.16
95604	400	428 S		MCGEE	ST	LOCAL	40	385	35	13,475		Coated Chip		\$2.95	\$4,372.64
95005	100	128 N		MCGEE	ST	LOCAL	46	293	30	8,790		Mill & Overlay		\$15.00	\$43,510.50
95536	700	728 S		MCGEE	ST	LOCAL	46	359	35	12,565		Mill & Overlay		\$15.00	\$62,196.75
95542	1100	1128 S		MCGEE	ST	LOCAL	47	350	35	12,250		Mill & Overlay		\$15.00	\$60,637.50
95599	300	328 S		MCGEE	ST	LOCAL	48	358	35	12,530		Mill & Overlay		\$15.00	\$62,023.50
95601	100	128 S		MCGEE	ST	LOCAL	49	360	35	12,600		Mill & Overlay		\$15.00	\$62,370.00
94761	200	230 N		MCGEE	ST	LOCAL	51	494	30	14,820		Mill & Overlay		\$15.00	\$73,359.00
95537	1000	1028 S		MCGEE	ST	LOCAL	51	370	35	12,950		Mill & Overlay		\$15.00	\$64,102.50
95541	900	928 S		MCGEE	ST	LOCAL	51	359	35	12,565		Mill & Overlay		\$15.00	\$62,196.75
95552	800	828 S		MCGEE	ST	LOCAL	51	358	35	12,530		Mill & Overlay		\$15.00	\$62,023.50
95080	900	930 N		MCGEE	ST	LOCAL	71	473	30	14,190		Crack Seal		\$0.75	\$1,170.68
94699	800	830 N		MCGEE	ST	LOCAL	78	464	30	13,920		Crack Seal		\$0.75	\$1,148.40
95099	700	730 N		MCGEE	ST	LOCAL	82	455	30	13,650		Crack Seal		\$0.75	\$1,126.13
95545	1200	1206 S		MCGEE	ST	LOCAL		208	35	7,280		Coated Chip		\$2.95	\$2,362.36
95596	500	528 S		MCGEE	ST	LOCAL		364	35	12,740		Coated Chip		\$2.95	\$4,134.13
95607	600	698 S		MCGEE	ST	LOCAL		361	35	12,635		Coated Chip		\$2.95	\$4,100.06
95612	200	228 S		MCGEE	ST	LOCAL		303	35	10,605		Coated Chip		\$2.95	\$3,441.32
95614	610	630 N		MCGEE	ST	LOCAL		310	35	10,850		Coated Chip		\$2.95	\$3,520.83
96936	600	608 N		MCGEE	ST	LOCAL		155	35	5,425		Coated Chip		\$2.95	\$1,760.41
													Total:	\$591,737.05	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
94824	700	728		MCPHERSON	ST	LOCAL		741	30	22,230		Uncoated Chip		\$2.50	\$6,113.25
95127	800	832		MCPHERSON	ST	LOCAL		923	30	27,690		Uncoated Chip		\$2.50	\$7,614.75
													Total:	\$13,728.00	
95926	2	100		MEDICAL	DR	LOCAL		2546	25	63,650		Crack Seal		\$0.75	\$5,251.13
													Total:	\$5,251.13	
96304	1000	1014		MEREDITH	ST	LOCAL		419	25	10,475		Uncoated Chip		\$2.50	\$2,880.63
96305	1016	1022		MEREDITH	ST	LOCAL		289	25	7,225		Uncoated Chip		\$2.50	\$1,986.88
96306	1024	1024		MEREDITH	ST	LOCAL		113	30	3,390		Uncoated Chip		\$2.50	\$932.25
96307	1026	1028		MEREDITH	ST	LOCAL		174	25	4,350		Uncoated Chip		\$2.50	\$1,196.25
													Total:	\$6,996.00	
94875	500	598		MICHIGAN	DR	LOCAL		612	35	21,420		Uncoated Chip		\$2.50	\$5,890.50
95671	400	498		MICHIGAN	DR	LOCAL		362	35	12,670		Uncoated Chip		\$2.50	\$3,484.25
													Total:	\$9,374.75	
96336	100	198		MIMOSA	ST	LOCAL		138	35	4,830		Uncoated Chip		\$2.50	\$1,328.25
													Total:	\$1,328.25	
94674	1100	1114		MINNESOTA	ST	LOCAL		513	25	12,825		Uncoated Chip		\$2.50	\$3,526.88
94756	1200	1224		MINNESOTA	ST	LOCAL		1055	25	26,375		Uncoated Chip		\$2.50	\$7,253.13
													Total:	\$10,780.00	
95675	600	620		MISSISSIPPI	AVE	LOCAL		1328	35	46,480		Coated Chip		\$2.95	\$15,082.76
97124	532	534		MISSISSIPPI	AVE	LOCAL		288	35	10,080		Coated Chip		\$2.95	\$3,270.96
													Total:	\$18,353.72	
94987	600	608		MISSOURI	ST	LOCAL	65	260	50	13,000		Uncoated Chip		\$2.50	\$3,575.00
95674	700	720		MISSOURI	ST	LOCAL	67	1034	50	51,700		Crack Seal		\$0.75	\$4,265.25
95103	528	594		MISSOURI	ST	LOCAL		259	35	9,065		Uncoated Chip		\$2.50	\$2,492.88
95672	500	526		MISSOURI	ST	LOCAL		323	35	11,305		Uncoated Chip		\$2.50	\$3,108.88
													Total:	\$13,442.00	
95139	1100	1198		MITCHELL	ST	LOCAL		514	30	15,420		Uncoated Chip		\$2.50	\$4,240.50
													Total:	\$4,240.50	
95466	1100	1110		MOCKINGBIRD	LN	LOCAL		1146	15	17,190		Uncoated Chip		\$2.50	\$4,727.25
													Total:	\$4,727.25	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
96337	100	198		MOHAWK	ST	LOCAL		160	35	5,600		None		\$0.00	\$0.00
													Total:	\$0.00	
94698	600	628		MONROE	ST	LOCAL		359	30	10,770		Uncoated Chip		\$2.50	\$2,961.75
94746	500	528		MONROE	ST	LOCAL		377	30	11,310		Uncoated Chip		\$2.50	\$3,110.25
95036	1000	1030		MONROE	ST	LOCAL		376	30	11,280		Uncoated Chip		\$2.50	\$3,102.00
95126	200	228		MONROE	ST	LOCAL		325	30	9,750		Uncoated Chip		\$2.50	\$2,681.25
95480	900	930		MONROE	ST	LOCAL		326	30	9,780		Uncoated Chip		\$2.50	\$2,689.50
95503	1100	1216		MONROE	ST	LOCAL		715	30	21,450		Uncoated Chip		\$2.50	\$5,898.75
95523	700	728		MONROE	ST	LOCAL		616	30	18,480		Uncoated Chip		\$2.50	\$5,082.00
95531	300	428		MONROE	ST	LOCAL		665	30	19,950		Uncoated Chip		\$2.50	\$5,486.25
													Total:	\$31,011.75	
94802	600	614		MONTANA	AVE	LOCAL		492	30	14,760		Uncoated Chip		\$2.50	\$4,059.00
94851	700	730		MONTANA	AVE	LOCAL		838	30	25,140		Uncoated Chip		\$2.50	\$6,913.50
													Total:	\$10,972.50	
94844	800	826		MOODY	ST	LOCAL		721	30	21,630		Uncoated Chip		\$2.50	\$5,948.25
94972	700	724		MOODY	ST	LOCAL		671	30	20,130		Uncoated Chip		\$2.50	\$5,535.75
95250	828	834		MOODY	ST	LOCAL		136	30	4,080		Uncoated Chip		\$2.50	\$1,122.00
													Total:	\$12,606.00	
94881	220	230		MORELAND	ST	LOCAL		622	35	21,770		Uncoated Chip		\$2.50	\$5,986.75
95780	212	218		MORELAND	ST	LOCAL		328	35	11,480		Uncoated Chip		\$2.50	\$3,157.00
95795	200	210		MORELAND	ST	LOCAL		628	30	18,840		Uncoated Chip		\$2.50	\$5,181.00
													Total:	\$14,324.75	
94884	900	936		NELSON	AVE	LOCAL		1191	30	35,730	1,001	Crack Seal		\$0.75	\$2,947.73
95021	800	800		NELSON	AVE	LOCAL	72	179	30	5,370		Crack Seal		\$0.75	\$443.03
													Total:	\$3,390.75	
95914	800	818		NONKEN	AVE	LOCAL		529	40	21,160		Uncoated Chip		\$2.50	\$5,819.00
													Total:	\$5,819.00	
95434	201	225		OAK	ST	LOCAL		821	40	32,840		Uncoated Chip		\$2.50	\$9,031.00
													Total:	\$9,031.00	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
94743	156	164	E	OCLA	ST	LOCAL		277	30	8,310	595	Uncoated Chip		\$2.50	\$2,285.25
96774	132	134	E	OCLA	ST	LOCAL	56	174	30	5,220		Uncoated Chip		\$2.50	\$1,435.50
95363	100	112	W	OCLA	ST	LOCAL	79	496	30	14,880		Crack Seal		\$0.75	\$1,227.60
95361	114	144	W	OCLA	ST	LOCAL	80	955	30	28,650		Crack Seal		\$0.75	\$2,363.63
95358	214	218	W	OCLA	ST	LOCAL		169	30	5,070		Uncoated Chip		\$2.50	\$1,394.25
96561	200	204	W	OCLA	ST	LOCAL		326	30	9,780		Uncoated Chip		\$2.50	\$2,689.50
96562	206	212	W	OCLA	ST	LOCAL		328	30	9,840		Uncoated Chip		\$2.50	\$2,706.00
96563	220	224	W	OCLA	ST	LOCAL		217	35	7,595		Uncoated Chip		\$2.50	\$2,088.63
96775	136	144	E	OCLA	ST	LOCAL		303	35	10,605		Uncoated Chip		\$2.50	\$2,916.38
96776	146	154	E	OCLA	ST	LOCAL		285	35	9,975		Uncoated Chip		\$2.50	\$2,743.13
													Total:	\$21,849.85	
95129	700	724		ODANIEL	ST	LOCAL		715	30	21,450		Uncoated Chip		\$2.50	\$5,898.75
95258	800	826		ODANIEL	ST	LOCAL		722	30	21,660		Uncoated Chip		\$2.50	\$5,956.50
													Total:	\$11,855.25	
94841	1100	1198		ODESSA	AVE	LOCAL		449	30	13,470		Uncoated Chip		\$2.50	\$3,704.25
													Total:	\$3,704.25	
95470	1200	1208		OHIO	AVE	LOCAL		659	20	13,180		Uncoated Chip		\$2.50	\$3,624.50
													Total:	\$3,624.50	
94676	700	998		OPAL	ST	LOCAL		1317	30	39,510	5,794	Coated Chip		\$2.95	\$12,821.00
													Total:	\$12,821.00	
94672	400	418		OZMER	ST	LOCAL		157	30	4,710		Uncoated Chip		\$2.50	\$1,295.25
95131	300	304		OZMER	ST	LOCAL		294	30	8,820		Uncoated Chip		\$2.50	\$2,425.50
95773	124	210		OZMER	ST	LOCAL		352	30	10,560		Uncoated Chip		\$2.50	\$2,904.00
95787	100	122		OZMER	ST	LOCAL		733	30	21,990		Uncoated Chip		\$2.50	\$6,047.25
													Total:	\$12,672.00	
95901	2	28		PANTEX	ST	LOCAL		1312	20	26,240		Uncoated Chip		\$2.50	\$7,216.00
													Total:	\$7,216.00	
95488	1200	1230		PARK	PL	LOCAL		235	30	7,050		Uncoated Chip		\$2.50	\$1,938.75
													Total:	\$1,938.75	
94897	1008	1028		PARKWAY	ST	LOCAL		192	35	6,720		Uncoated Chip		\$2.50	\$1,848.00
95670	900	928		PARKWAY	ST	LOCAL		336	35	11,760		Uncoated Chip		\$2.50	\$3,234.00
													Total:	\$5,082.00	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
94733	1300	1324		PATTON	CIR	LOCAL		711	30	21,330		Uncoated Chip		\$2.50	\$5,865.75
													Total:	\$5,865.75	
95442	101	133		PECAN	ST	LOCAL		1166	30	34,980		Uncoated Chip		\$2.50	\$9,619.50
													Total:	\$9,619.50	
94835	285	299		PEIFFER	ST	LOCAL		165	30	4,950		Uncoated Chip		\$2.50	\$1,361.25
95801	100	130		PEIFFER	ST	LOCAL		847	30	25,410		Uncoated Chip		\$2.50	\$6,987.75
95853	210	234		PEIFFER	ST	LOCAL		364	30	10,920		Uncoated Chip		\$2.50	\$3,003.00
96798	200	208		PEIFFER	ST	LOCAL		322	30	9,660		Uncoated Chip		\$2.50	\$2,656.50
													Total:	\$14,008.50	
95298	1576	1598		PELLINORE	ST	LOCAL		1395	15	20,925		Uncoated Chip		\$2.50	\$5,754.38
95774	1500	1524		PELLINORE	ST	LOCAL		687	30	20,610		Uncoated Chip		\$2.50	\$5,667.75
													Total:	\$11,422.13	
95463	1000	1024		PENN	ST	LOCAL		357	25	8,925		Uncoated Chip		\$2.50	\$2,454.38
95464	1100	1114		PENN	ST	LOCAL		516	50	25,800		Uncoated Chip		\$2.50	\$7,095.00
													Total:	\$9,549.38	
95436	101	107		PHILVIEW	AVE	LOCAL		255	40	10,200		Coated Chip		\$2.95	\$3,309.90
95437	201	205		PHILVIEW	AVE	LOCAL		259	30	7,770		Coated Chip		\$2.95	\$2,521.37
95438	350	448		PHILVIEW	AVE	LOCAL		268	30	8,040		Coated Chip		\$2.95	\$2,608.98
96759	207	219		PHILVIEW	AVE	LOCAL		264	30	7,920		Coated Chip		\$2.95	\$2,570.04
96770	460	498		PHILVIEW	AVE	LOCAL		558	30	16,740		Coated Chip		\$2.95	\$5,432.13
96771	450	458		PHILVIEW	AVE	LOCAL		335	20	6,700		Coated Chip		\$2.95	\$2,174.15
													Total:	\$18,616.57	
95532	700	728		PINE	ST	LOCAL		364	35	12,740		Uncoated Chip		\$2.50	\$3,503.50
95534	1200	1248		PINE	ST	LOCAL		805	25	20,125		Uncoated Chip		\$2.50	\$5,534.38
95538	1000	1028		PINE	ST	LOCAL		357	30	10,710		Uncoated Chip		\$2.50	\$2,945.25
95547	1100	1128		PINE	ST	LOCAL		356	35	12,460		Uncoated Chip		\$2.50	\$3,426.50
95551	900	928		PINE	ST	LOCAL		355	30	10,650		Uncoated Chip		\$2.50	\$2,928.75
													Total:	\$18,338.38	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
95415	100	112		PINEHURST	ST	LOCAL		641	30	19,230		Uncoated Chip		\$2.50	\$5,288.25
95416	200	210		PINEHURST	ST	LOCAL		637	30	19,110		Uncoated Chip		\$2.50	\$5,255.25
95417	300	310		PINEHURST	ST	LOCAL		649	30	19,470		Uncoated Chip		\$2.50	\$5,354.25
													Total:	\$15,897.75	
95443	101	129		PINON	ST	LOCAL		1080	30	32,400		Uncoated Chip		\$2.50	\$8,910.00
													Total:	\$8,910.00	
95243	712	726		PLATT	ST	LOCAL		430	30	12,900		Uncoated Chip		\$2.50	\$3,547.50
													Total:	\$3,547.50	
95806	200	698		PLUM	DR	LOCAL		2499	20	49,980		None		\$0.00	\$0.00
													Total:	\$0.00	
97012	0	0		POTTER	AVE	LOCAL		1149	30	34,470		Uncoated Chip		\$2.50	\$9,479.25
													Total:	\$9,479.25	
94780	2600	2698		PRAIRIE	ST	LOCAL		314	10	3,140		Crack Seal		\$0.75	\$259.05
													Total:	\$259.05	
94784	1602	1610		PRIMROSE	LN	LOCAL		450	30	13,500		Coated Chip		\$2.95	\$4,380.75
95797	1400	1422		PRIMROSE	LN	LOCAL		848	30	25,440		Coated Chip		\$2.95	\$8,255.28
95836	1514	1600		PRIMROSE	LN	LOCAL		492	30	14,760		Coated Chip		\$2.95	\$4,789.62
96301	1500	1510		PRIMROSE	LN	LOCAL		372	30	11,160		Coated Chip		\$2.95	\$3,621.42
96302	1512	1512		PRIMROSE	LN	LOCAL		153	30	4,590		Coated Chip		\$2.95	\$1,489.46
													Total:	\$22,536.53	
97237	0	0		QUAIL HOLLOW		LOCAL		450	70	31,500		Uncoated Chip		\$2.50	\$8,662.50
													Total:	\$8,662.50	
95289	0	0		QUAIL RIDGE		LOCAL		612	20	12,240		Uncoated Chip		\$2.50	\$3,366.00
													Total:	\$3,366.00	
95789	200	208		RICE	ST	LOCAL		357	30	10,710		Uncoated Chip		\$2.50	\$2,945.25
95808	100	108		RICE	ST	LOCAL		359	30	10,770		Uncoated Chip		\$2.50	\$2,961.75
													Total:	\$5,907.00	
94701	100	102		RIGDON	ST	LOCAL		144	35	5,040		Uncoated Chip		\$2.50	\$1,386.00
95783	104	128		RIGDON	ST	LOCAL		826	35	28,910		Uncoated Chip		\$2.50	\$7,950.25
													Total:	\$9,336.25	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
94966	100	118		RILEY		LOCAL		479	20	9,580		Uncoated Chip		\$2.50	\$2,634.50
													Total:	\$2,634.50	
95729	1200	1228		ROBERTS	ST	LOCAL		834	25	20,850		Uncoated Chip		\$2.50	\$5,733.75
97015	1230	1248		ROBERTS	ST	LOCAL		396	25	9,900		Uncoated Chip		\$2.50	\$2,722.50
													Total:	\$8,456.25	
94673	1500	1550		ROOSEVELT	ST	LOCAL		1828	50	91,400	28,030	Crack Seal		\$0.75	\$7,540.50
95500	1100	1114		ROOSEVELT	ST	LOCAL	67	719	30	21,570	19,576	Crack Seal		\$0.75	\$1,779.53
94796	1300	1398		ROOSEVELT	ST	LOCAL		700	40	28,000	18,303	Crack Seal		\$0.75	\$2,310.00
94995	1000	1030		ROOSEVELT	ST	LOCAL	69	365	35	12,775	17,768	Crack Seal		\$0.75	\$1,053.94
94958	900	930		ROOSEVELT	ST	LOCAL		337	35	11,795	17,553	Crack Seal		\$0.75	\$973.09
94941	500	528		ROOSEVELT	ST	LOCAL		377	30	11,310		Coated Chip		\$2.95	\$3,670.10
95038	600	628		ROOSEVELT	ST	LOCAL		359	30	10,770		Coated Chip		\$2.95	\$3,494.87
95519	700	728		ROOSEVELT	ST	LOCAL		620	30	18,600		Coated Chip		\$2.95	\$6,035.70
95527	300	328		ROOSEVELT	ST	LOCAL		561	30	16,830		Coated Chip		\$2.95	\$5,461.34
													Total:	\$32,319.05	
95022	300	302		SALINA	ST	LOCAL		325	30	9,750		Uncoated Chip		\$2.50	\$2,681.25
95356	100	108		SALINA	ST	LOCAL		1297	35	45,395		Uncoated Chip		\$2.50	\$12,483.63
95357	220	236		SALINA	ST	LOCAL		683	35	23,905		Uncoated Chip		\$2.50	\$6,573.88
97104	304	304		SALINA	ST	LOCAL		166	30	4,980		Uncoated Chip		\$2.50	\$1,369.50
													Total:	\$23,108.25	
96338	300	304		SAN JUAN	WAY	LOCAL		203	30	6,090		Uncoated Chip		\$2.50	\$1,674.75
													Total:	\$1,674.75	
95288	2	4		SANDSTONE	DR	LOCAL		365	30	10,950		Uncoated Chip		\$2.50	\$3,011.25
													Total:	\$3,011.25	
95782	300	318		SANTA FE	ST	LOCAL		509	30	15,270		Uncoated Chip		\$2.50	\$4,199.25
95788	200	220		SANTA FE	ST	LOCAL		570	30	17,100		Uncoated Chip		\$2.50	\$4,702.50
96975	426	434		SANTA FE	ST	LOCAL		774	30	23,220		Uncoated Chip		\$2.50	\$6,385.50
													Total:	\$15,287.25	
95347	200	210		SARASOTA	ST	LOCAL		474	35	16,590		Uncoated Chip		\$2.50	\$4,562.25
95362	100	104		SARASOTA	ST	LOCAL		310	35	10,850		Uncoated Chip		\$2.50	\$2,983.75
95405	300	302		SARASOTA	ST	LOCAL		314	30	9,420		Uncoated Chip		\$2.50	\$2,590.50
96891	304	308		SARASOTA	ST	LOCAL		146	35	5,110		Uncoated Chip		\$2.50	\$1,405.25
													Total:	\$11,541.75	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
95876	500	514		SHORT	ST	LOCAL		384	20	7,680		Uncoated Chip		\$2.50	\$2,112.00
													Total:	\$2,112.00	
95360	100	104		SKYCREST	ST	LOCAL		317	35	11,095		Uncoated Chip		\$2.50	\$3,051.13
95411	106	228		SKYCREST	ST	LOCAL		1481	35	51,835		Uncoated Chip		\$2.50	\$14,254.63
													Total:	\$17,305.75	
95859	106	114		SMITH	ST	LOCAL		417	30	12,510		Uncoated Chip		\$2.50	\$3,440.25
													Total:	\$3,440.25	
95413	200	244		SOMERSET	ST	LOCAL	53	1724	35	60,340		Uncoated Chip		\$2.50	\$16,593.50
95359	100	106		SOMERSET	ST	LOCAL		316	30	9,480		Uncoated Chip		\$2.50	\$2,607.00
95412	300	310		SOMERSET	ST	LOCAL		162	35	5,670		Uncoated Chip		\$2.50	\$1,559.25
													Total:	\$20,759.75	
95533	1100	1128		SPRUCE	ST	LOCAL		350	30	10,500		Uncoated Chip		\$2.50	\$2,887.50
95535	900	928		SPRUCE	ST	LOCAL		363	30	10,890		Uncoated Chip		\$2.50	\$2,994.75
95539	700	728		SPRUCE	ST	LOCAL		362	35	12,670		Uncoated Chip		\$2.50	\$3,484.25
95540	1000	1028		SPRUCE	ST	LOCAL		366	30	10,980		Uncoated Chip		\$2.50	\$3,019.50
95543	800	828		SPRUCE	ST	LOCAL		360	30	10,800		Uncoated Chip		\$2.50	\$2,970.00
95595	600	624		SPRUCE	ST	LOCAL		363	30	10,890		Uncoated Chip		\$2.50	\$2,994.75
													Total:	\$18,350.75	
95343	100	110		ST JAMES	ST	LOCAL		303	30	9,090		Uncoated Chip		\$2.50	\$2,499.75
													Total:	\$2,499.75	
94722	100	398		ST JOHNS	RD	LOCAL		1171	35	40,985		Uncoated Chip		\$2.50	\$11,270.88
													Total:	\$11,270.88	
94989	700	718 W		STEPHENS	DR	LOCAL	59	472	25	11,800	1,385	Uncoated Chip		\$2.50	\$3,245.00
94915	800	818 W		STEPHENS	DR	LOCAL		442	25	11,050		Uncoated Chip		\$2.50	\$3,038.75
													Total:	\$6,283.75	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
95700	1300	1324		STERLING	ST	LOCAL	56	1316	30	39,480	2,938	Coated Chip		\$2.95	\$12,811.26
95057	1600	1630		STERLING	ST	LOCAL	58	385	20	7,700	1,499	Coated Chip		\$2.95	\$2,498.65
95056	1000	1048		STERLING	ST	LOCAL	50	184	35	6,440		Coated Chip		\$2.95	\$2,089.78
94847	1100	1116		STERLING	ST	LOCAL	52	651	30	19,530		Coated Chip		\$2.95	\$6,337.49
94757	1700	1720		STERLING	ST	LOCAL	68	950	25	23,750		Crack Seal		\$0.75	\$1,959.38
94763	800	848		STERLING	ST	LOCAL		272	30	8,160		Coated Chip		\$2.95	\$2,647.92
94846	900	948		STERLING	ST	LOCAL		323	20	6,460		Coated Chip		\$2.95	\$2,096.27
94870	700	748		STERLING	ST	LOCAL		315	30	9,450		Coated Chip		\$2.95	\$3,066.53
95254	608	626		STERLING	ST	LOCAL		319	30	9,570		Coated Chip		\$2.95	\$3,105.47
95272	756	798		STERLING	ST	LOCAL		66	35	2,310		Coated Chip		\$2.95	\$749.60
97005	1200	1206		STERLING	ST	LOCAL		315	30	9,450		Coated Chip		\$2.95	\$3,066.53
													Total:	\$40,428.85	
95083	600	724		STEVENSON	ST	LOCAL		755	30	22,650		Uncoated Chip		\$2.50	\$6,228.75
													Total:	\$6,228.75	
94992	1800	1820		TAKEWELL	ST	LOCAL		298	25	7,450		Uncoated Chip		\$2.50	\$2,048.75
95017	1700	1706		TAKEWELL	ST	LOCAL		298	25	7,450		Uncoated Chip		\$2.50	\$2,048.75
95705	1600	1616		TAKEWELL	ST	LOCAL		522	25	13,050		Uncoated Chip		\$2.50	\$3,588.75
96990	1618	1624		TAKEWELL	ST	LOCAL		304	25	7,600		Uncoated Chip		\$2.50	\$2,090.00
													Total:	\$9,776.25	
94771	2	98		TAYLOR	ST	LOCAL		390	30	11,700		Uncoated Chip		\$2.50	\$3,217.50
													Total:	\$3,217.50	
95784	100	128		TEAGUE	ST	LOCAL		815	30	24,450		Uncoated Chip		\$2.50	\$6,723.75
95804	200	224		TEAGUE	ST	LOCAL		675	30	20,250		Uncoated Chip		\$2.50	\$5,568.75
													Total:	\$12,292.50	
95817	100	108		TECH	ST	LOCAL		756	30	22,680		Uncoated Chip		\$2.50	\$18,711.00
95842	216	228		TECH	ST	LOCAL		332	30	9,960		Uncoated Chip		\$2.50	\$8,217.00
													Total:	\$26,928.00	
94988	1200	1398		TEJAS	DR	LOCAL		515	65	33,475		Uncoated Chip		\$2.50	\$9,205.63
													Total:	\$9,205.63	
95874	100	120		TEXAS	ST	LOCAL		506	30	15,180		Uncoated Chip		\$2.50	\$4,174.50
													Total:	\$4,174.50	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
95733	1210	1230		THOMPSON	AVE	LOCAL		658	25	16,450		Uncoated Chip		\$2.50	\$4,523.75
95734	1100	1198		THOMPSON	AVE	LOCAL		231	25	5,775		Uncoated Chip		\$2.50	\$1,588.13
95735	1250	1298		THOMPSON	ST	LOCAL		239	15	3,585		Uncoated Chip		\$2.50	\$985.88
96790	1200	1208		THOMPSON	AVE	LOCAL		373	25	9,325		Uncoated Chip		\$2.50	\$2,564.38
96791	1232	1248		THOMPSON	AVE	LOCAL		244	25	6,100		Uncoated Chip		\$2.50	\$1,677.50
													Total:	\$11,339.63	
95681	1000	1040		THRAMS	ST	LOCAL		1212	25	30,300		Uncoated Chip		\$2.50	\$8,332.50
													Total:	\$8,332.50	
95352	100	118		TIERRA ALTO	DR	LOCAL		337	30	10,110		Crack Seal		\$0.75	\$834.08
													Total:	\$834.08	
97239	100	110		TIMBERLAKE	CT	LOCAL		600	30	18,000		Uncoated Chip		\$2.50	\$4,950.00
													Total:	\$4,950.00	
95776	200	298		TRISTRAM	ST	LOCAL		297	30	8,910	12,150	Coated Chip		\$2.95	\$2,891.30
95770	610	620		TRISTRAM	ST	LOCAL		330	30	9,900	3,189	Coated Chip		\$2.95	\$3,212.55
95821	100	148		TRISTRAM	ST	LOCAL	58	240	35	8,400		Coated Chip		\$2.95	\$2,725.80
95822	2	98		TRISTRAM	ST	LOCAL	61	692	25	17,300		Coated Chip		\$2.95	\$5,613.85
94688	400	498		TRISTRAM	ST	LOCAL		289	35	10,115		Coated Chip		\$2.95	\$3,282.32
94764	600	608		TRISTRAM	ST	LOCAL		296	30	8,880		Coated Chip		\$2.95	\$2,881.56
95772	150	198		TRISTRAM	ST	LOCAL		214	30	6,420		Coated Chip		\$2.95	\$2,083.29
95779	300	398		TRISTRAM	ST	LOCAL		310	35	10,850		Coated Chip		\$2.95	\$3,520.83
95796	500	598		TRISTRAM	ST	LOCAL		303	35	10,605		Coated Chip		\$2.95	\$3,441.32
													Total:	\$29,652.81	
94821	1400	1410		TURNER	ST	LOCAL	49	450	30	13,500	493	Uncoated Chip		\$2.50	\$3,712.50
94825	100	134		TURNER	ST	LOCAL	57	903	25	22,575		Uncoated Chip		\$2.50	\$6,208.13
95717	1300	1324		TURNER	ST	LOCAL		488	30	14,640		Uncoated Chip		\$2.50	\$4,026.00
96957	1338	1350		TURNER	ST	LOCAL		575	35	20,125		Uncoated Chip		\$2.50	\$5,534.38
													Total:	\$19,481.00	
94946	900	930		TYLER	ST	LOCAL		333	25	8,325		Uncoated Chip		\$2.50	\$2,289.38
96978	1000	1010		TYLER	ST	LOCAL		420	35	14,700		Uncoated Chip		\$2.50	\$12,127.50
													Total:	\$14,416.88	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
96268	100	120		UNION	ST	LOCAL		563	30	16,890	15,514	Crack Seal		\$0.75	\$1,393.43
95790	200	218		UNION	ST	LOCAL	68	549	30	16,470	4,257	Crack Seal		\$0.75	\$1,358.78
96972	426	436		UNION	ST	LOCAL		417	30	12,510	4,180	Coated Chip		\$2.95	\$4,059.50
95848	412	422		UNION	ST	LOCAL		329	35	11,515		Coated Chip		\$2.95	\$3,736.62
95849	308	318		UNION	ST	LOCAL		314	35	10,990		Coated Chip		\$2.95	\$3,566.26
96793	300	306		UNION	ST	LOCAL		305	35	10,675		Coated Chip		\$2.95	\$3,464.04
96973	424	424		UNION	ST	LOCAL		279	30	8,370		Coated Chip		\$2.95	\$2,716.07
96974	400	410		UNION	ST	LOCAL		291	35	10,185		Coated Chip		\$2.95	\$3,305.03
													Total:	\$23,599.70	
95482	1200	1230		UNIVERSITY	PL	LOCAL		243	15	3,645		Uncoated Chip		\$2.50	\$1,002.38
													Total:	\$1,002.38	
95736	1200	1298		VALLEY	DR	LOCAL		70	85	5,950		Uncoated Chip		\$2.50	\$1,636.25
95743	1114	1134		VALLEY	DR	LOCAL		585	25	14,625		Uncoated Chip		\$2.50	\$4,021.88
96949	1100	1112		VALLEY	DR	LOCAL		434	25	10,850		Uncoated Chip		\$2.50	\$2,983.75
													Total:	\$8,641.88	
94840	200	208		VETA	ST	LOCAL		347	30	10,410		Uncoated Chip		\$2.50	\$2,862.75
95101	100	120		VETA	ST	LOCAL		140	35	4,900		Uncoated Chip		\$2.50	\$1,347.50
													Total:	\$4,210.25	
95441	0	0		WALNUT	ST	LOCAL		1642	20	32,840		Uncoated Chip		\$2.50	\$9,031.00
													Total:	\$9,031.00	
95880	101	111		WARNER	ST	LOCAL		380	30	11,400		Uncoated Chip		\$2.50	\$3,135.00
													Total:	\$3,135.00	
95402	200	208		WARWICK	ST	LOCAL		330	30	9,900		Uncoated Chip		\$2.50	\$2,722.50
95403	108	118		WARWICK	ST	LOCAL		329	30	9,870		Uncoated Chip		\$2.50	\$2,714.25
96695	211	225		WARWICK	ST	LOCAL		316	30	9,480		Uncoated Chip		\$2.50	\$2,607.00
96698	100	106		WARWICK	ST	LOCAL		327	35	11,445		Uncoated Chip		\$2.50	\$3,147.38
96699	120	126		WARWICK	ST	LOCAL		305	35	10,675		Uncoated Chip		\$2.50	\$2,935.63
													Total:	\$14,126.75	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost Cost	Total Segment Repair Cost
94919	900	930		WEATHERLY	ST	LOCAL	63	481	40	19,240	9,149	Coated Chip		\$2.95	\$6,243.38
94686	400	436		WEATHERLY	ST	LOCAL		453	40	18,120	8,452	Coated Chip		\$2.95	\$5,879.94
94855	300	330		WEATHERLY	ST	LOCAL	62	435	40	17,400		Coated Chip		\$2.95	\$5,646.30
94981	500	532		WEATHERLY	ST	LOCAL	62	471	40	18,840		Coated Chip		\$2.95	\$6,113.58
94725	600	630		WEATHERLY	ST	LOCAL	66	459	40	18,360		Crack Seal		\$0.75	\$1,514.70
94742	800	830		WEATHERLY	ST	LOCAL	66	460	40	18,400		Crack Seal		\$0.75	\$1,518.00
94945	700	730		WEATHERLY	ST	LOCAL	67	457	40	18,280		Crack Seal		\$0.75	\$1,508.10
94689	100	128		WEATHERLY	ST	LOCAL		299	30	8,970		Coated Chip		\$2.95	\$2,910.77
95037	200	230		WEATHERLY	ST	LOCAL		486	30	14,580		Coated Chip		\$2.95	\$4,731.21
													Total:	\$36,065.98	
95691	900	928		WEST	DR	LOCAL		1033	30	30,990		Uncoated Chip		\$2.50	\$8,522.25
													Total:	\$8,522.25	
94979	800	814		WESTERN	AVE	LOCAL		337	25	8,425		Uncoated Chip		\$2.50	\$2,316.88
95684	910	936		WESTERN	AVE	LOCAL		894	25	22,350		Uncoated Chip		\$2.50	\$6,146.25
													Total:	\$8,463.13	
95074	500	598		WHITE	ST	LOCAL		654	25	16,350		Uncoated Chip		\$2.50	\$4,496.25
													Total:	\$4,496.25	
95141	500	530		WHITLOW	ST	LOCAL		490	25	12,250		Uncoated Chip		\$2.50	\$3,368.75
													Total:	\$3,368.75	
94769	300	330		WHITTENBURG	ST	LOCAL		429	30	12,870		Uncoated Chip		\$2.50	\$3,539.25
94775	400	430		WHITTENBURG	ST	LOCAL		460	30	13,800		Uncoated Chip		\$2.50	\$3,795.00
94810	100	128		WHITTENBURG	ST	LOCAL		297	45	13,365		Uncoated Chip		\$2.50	\$3,675.38
94882	800	832		WHITTENBURG	ST	LOCAL		456	30	13,680		Uncoated Chip		\$2.50	\$3,762.00
94912	600	630		WHITTENBURG	ST	LOCAL		463	30	13,890		Uncoated Chip		\$2.50	\$3,819.75
94968	500	532		WHITTENBURG	ST	LOCAL		470	30	14,100		Uncoated Chip		\$2.50	\$3,877.50
94974	200	230		WHITTENBURG	ST	LOCAL		486	30	14,580		Uncoated Chip		\$2.50	\$4,009.50
95054	700	730		WHITTENBURG	ST	LOCAL		462	30	13,860		Uncoated Chip		\$2.50	\$3,811.50
95241	900	930		WHITTENBURG	ST	LOCAL		480	30	14,400		Uncoated Chip		\$2.50	\$3,960.00
													Total:	\$34,249.88	
95137	700	718		WILLIAMS	ST	LOCAL		307	25	7,675		Uncoated Chip		\$2.50	\$2,110.63
													Total:	\$2,110.63	

ID	Right Block Start	Right Block End	Direction	Name	Type	RoadClass	PCI Score	Length	Width	Total Area	Weekly Traffic Count	Repair Method	Curb Repair	Repair Unit Cost	Total Segment Repair Cost
95423	120	128		WILLOWICK	ST	LOCAL		297	30	8,910	1,164	Uncoated Chip		\$2.50	\$2,450.25
96777	100	108		WILLOWICK	ST	LOCAL		339	30	10,170	1,164	Uncoated Chip		\$2.50	\$2,796.75
96778	110	118		WILLOWICK	ST	LOCAL		329	30	9,870	1,164	Uncoated Chip		\$2.50	\$2,714.25
96779	130	136		WILLOWICK	ST	LOCAL		297	30	8,910	1,164	Uncoated Chip		\$2.50	\$2,450.25
													Total:	\$10,411.50	
95421	118	142		WILSHIRE	ST	LOCAL		783	30	23,490	751	Uncoated Chip		\$2.50	\$6,459.75
96780	100	116		WILSHIRE	ST	LOCAL		655	35	22,925	751	Uncoated Chip		\$2.50	\$6,304.38
													Total:	\$12,764.13	
94907	100	198 E		WILSON	ST	LOCAL	27	371	45	16,695		Mill & Overlay		\$15.00	\$82,640.25
95555	200	228 W		WILSON	ST	LOCAL	55	656	30	19,680		Coated Chip		\$2.95	\$6,386.16
95584	300	328 W		WILSON	ST	LOCAL	67	656	30	19,680		Crack Seal		\$0.75	\$1,623.60
96986	300	398 E		WILSON	ST	LOCAL		659	30	19,770		Coated Chip		\$2.95	\$6,415.37
													Total:	\$97,065.38	
95471	1300	1318		WISCONSIN	ST	LOCAL		323	30	9,690		Uncoated Chip		\$2.50	\$2,664.75
95472	1200	1224		WISCONSIN	ST	LOCAL		1003	30	30,090		Uncoated Chip		\$2.50	\$8,274.75
													Total:	\$10,939.50	
95791	100	138		WOMACK	ST	LOCAL		1094	30	32,820		Uncoated Chip		\$2.50	\$9,025.50
													Total:	\$9,025.50	
95723	1300	1314		YOWS	ST	LOCAL	61	512	30	15,360		Uncoated Chip		\$2.50	\$4,224.00
94704	1116	1138		YOWS	ST	LOCAL	65	283	35	9,905		Uncoated Chip		\$2.50	\$2,723.88
94894	1208	1262		YOWS	ST	LOCAL	67	299	30	8,970		Crack Seal		\$0.75	\$740.03
95135	1200	1204		YOWS	ST	LOCAL	70	430	30	12,900		Crack Seal		\$0.75	\$1,064.25
95065	1000	1018		YOWS	ST	LOCAL		317	35	11,095		Uncoated Chip		\$2.50	\$3,051.13
95715	1502	1508		YOWS	ST	LOCAL		267	30	8,010		Uncoated Chip		\$2.50	\$2,202.75
95879	1800	1804		YOWS	ST	LOCAL		291	30	8,730		Uncoated Chip		\$2.50	\$2,400.75
96964	1600	1602		YOWS	ST	LOCAL		285	30	8,550		Uncoated Chip		\$2.50	\$2,351.25
96965	1700	1700		YOWS	ST	LOCAL		194	30	5,820		Uncoated Chip		\$2.50	\$1,600.50
													Total:	\$20,358.53	
													Total Estimate Repair Cost	\$9,280,634.36	